

TECHNICAL SERVICE BULLETIN

To: All Powerboss Dealers and Service Managers

From: PowerBoss Technical Support

Date: 3-1-2019

Subject: TSB for New Laptop Interface pigtail (690210)

Reason for Change


The diagnostics connector on the engine has changed due to an update in the engine wire harness from Kubota and will need the new pigtail **WITH** the standard interface cable to connect to engine for diagnostics troubleshooting.

Improvement

Needed to connect to engine diagnostic connector. If you have ordered the standard interface cable from PBoss please get in contact with us regarding this update.

Models/Serial Numbers Affected

All Kubota WG1605 LPG and GAS engines.



Reference Kit Instructions – Product Information.

Informational Only For Purchase Warranty Product Improvement