
DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 1 DATE: APR. 24, 2000



Insert 8ea. Grommet(3311564) into Plate(3311311) as shown.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 2 DATE: APR. 24, 2000





TOOLS: FLATHEAD SCREWDRIVER

Attach 2ea. Angle(3311420) to 2ea. Contactor-Main(3311018) with 2ea. Scr-Thm(3400322). Tighten with flathead screwdriver. **NOTE the position of the angle on each of the contactor.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 3 DATE: APR. 24, 2000

TOOLS:5/16 WRENCH, 3/8 WRENCH



Attach Resistor(3311019) with 2ea. Scr-Hex(3400315) and 2ea. Nut-Hex(3400172). Tighten with 5/16 wrench and 3/8 wrench.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 4 DATE: APR. 24, 2000







Secure both contactor with 2ea. Scr-Hex(3400315) and 2ea. Nut-Hex(3400172). Tighten with 5/16 wrench and 3/8 wrench.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 5 DATE: APR. 24, 2000



TOOLS: 7/16 WRENCH, 7/16 SOCKET

Attach Controller(3311016) with 4ea. Scr-Hex(3400042) and 4ea. Nut-Hex(3400081). Tighten with 7/16 socket and 7/16 wrench.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 6

DATE: APR. 24, 2000 TOOLS: FLATHEAD SCREWDRIVER, 11/32 WRENCH






Attach 2ea. Mnt(3311421) with 2ea. Scr-Pan(3400045) and 2ea. Nut-Hex(3400082). Tighten with flathead screwdriver and 11/32 wrench. Attach Resistor(3311567) as shown.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 7 DATE: APR. 24, 2000





TOOLS: 7/16 SOCKET, 7/16 WRENCH

Attach Cable-Battery(3311440) to Bracket(3311568) with 2ea. Scr-Hex(3400227), Nut-Hex(3400081). Tighten with 7/16 socket, 7/16 wrench. Attach battery/bracket to plate with 2ea. Scr-Hex(3400042) and 2ea. Nut-Hex(3400081). Tighten with 7/16 socket and 7/16 wrench.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 8 DATE: APR. 24, 2000







Place Resistor(3311020) and Cable(3311441)onto Contactor as shown.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 9 DATE: APR. 24, 2000








TOOLS: 1/2 WRENCH

REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS


PAGE NUMBER: 10 DATE: APR. 24, 2000



REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 11 DATE: APR. 24, 2000



REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS


PAGE NUMBER: 12 DATE: APR. 24, 2000



REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS


PAGE NUMBER: 13 DATE: APR. 24, 2000



REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS


PAGE NUMBER: 14 DATE: APR. 24, 2000



REFER TO WIRING DIAGRAM.

DOCUMENTED BY: POWERBOSS


PAGE NUMBER: 15 DATE: APR. 24, 2000



Attach male end to wires and crimp to fit. Apply heatshrink as shown. **REFER TO WIRING DIAGRAM.**

DOCUMENTED BY: POWERBOSS

PAGE NUMBER: 16 DATE: APR. 24, 2000



COMPLETE