IEB Industrie Elektronik Brilon
Energy Systems

Industrie
ELEKTRONIK
Brilon GmbH

Charge settings
IEB 770 36V/120A
Type: Z 400 G 36/120 B30-FP

Quick guide

	action	pause-button	charger response
1	plug in mains plug (without batterie)	-	standby-mode (white LED lights)
2	switch off charger	3s	Off-State (white LED flashes all 4 seconds)
3	programming mode	10s	programming mode active
4	select characteristic curve until desired characteristic curve is displayed (according to characteristic curve table)	short	active program flashes quickly, inactive slowly
5	save characteristic curve	5s	program flashes quickly and is saved
6	exit programming mode (alternatively wait 60s)	1,5s…3s	Off-State (white LED flashes all 4 seconds)
7	activate standby mode (alternatively wait 15s)	short	standby-mode (white LED lights)
8	connect battery	-	charging with set program is started

program 0: PzS 320Ah
program 1: PzS 480Ah
program 2: PzS 540Ah
program 3: PzS 810Ah