




Warning beacon on pole, upgrade option (99650505) ->

85-00-1993-770_1

Pos.	Part-No.	Material-No.	Description	Measurement	DIN/ISO	Serial No. begin	Serial No. end	valid from	valid until	Remarks	Qty.	Unit
1	01135440	90422684	Warning beacon	LT 4xMV/2							1	PC
2	01135470	19719517	pin housing								1	PC
3	01135460	19256080	switch warning beacon								1	PC
4	00906120	19731181	Fuse	C5A T3	DIN 72581						1	PC
5	00967760	90156688	Cable tie	4,8x360							5	PC
6	00121150	90114810	Cable tie	T25L 2, 8x240-PA66-natur							10	PC
7	01135450	19719368	plug body								1	PC
8	00053720	12310025	Washer	5-200HV-N2	ISO 7089						2	PC
9	00705480	15592017	Lens cap	1000/1068 SW							2	PC
10	01135480	96099908	lampholder								1	PC
11	00740290	12520061	Detent edged washer	SKM-10							3	PC
12	00053310	11038346	hexagon screw	M10x25-8.8-N3	ISO 4017						3	PC
13	00747210	15592041	Lens cap	1000/1072 SW							4	PC
14	00053160	11038379	hexagon screw	M10x30-8.8-N3	ISO 4017						3	PC
15	00053760	12310058	Washer	10-200HV-N3	ISO 7089						3	PC
16	01145160	12040291	Hex. Nut	M10-8 A2G	DIN 985						3	PC
17	01006210	19719293	Pin contact	0,3-0,5							2	PC
18	00903570	19719160	Bushing contact	1,0-1,5							2	PC
19	01006190	19719319	Seal	1,4-1,7							2	PC
W9	03026220	97081236	wiring harness W9								1	PC