


		CODE:		wd27185-1 aa SN from 98L010	
DESCRIPTION:	WIRING DIAGRAM	SCHALTPLAN	SCHEMA ELECTRIQUE	ESQUEMA ELECTICO	SCHEMA Elett. FUNZIONALE



REF	CODE	DESCRIPTION	QT
AP1		PUMP BOARD	
AP2		DRIVE MOTOR BOARD	
BL1		SWITCH	
FR.M1		THERMAL M1	
FR.M4		THERMAL M4	
FU1		FUSE 75A	
FU2		FUSE 5A	
FU3		FUSE 5A	
FU4		FUSE 25A	
FU5		FUSE 40A	
GB1		BATTERY	
GD		CHARGER (optional)	
HL1		LAMP	
JP1..JP4		ELECTRIC CONNECTION	
KM1		BRUSH REMOTE CONTROL SWITCH	
M1		BRUSH MOTOR	
M2		SUCTION MOTOR	
M3		PUMP	
M4		DRIVE MOTOR	
QF1		SWITCH	
R1		RESISTANCE 10 Ohm 1/2 W	
RP1		POTENTIOMETER	
SA1		SWITCH M1 ON/OFF	
SA2		SWITCH M2 ON/OFF	
SA3		SWITCH M3 ON/OFF	
SA4		MICROSWITCH	
SR1		MICROSWITCH	
VD1		DIODE	
XP1		CONNECTOR	
XP2		CONNECTOR M.	
XS2		CONNECTOR F.	
XP3		CONNECTOR M.	
XS3		CONNECTOR F.	
XP4		CONNECTOR M.	
XS4		CONNECTOR F.	
XS5		CONNECTOR F.	
XP7		CONNECTOR M.	
XP8		CONNECTOR M.	
XP9		CONNECTOR M.	
XP10		CONNECTOR M.	
XP11		CONNECTOR M.	
XP12		CONNECTOR M.	
XS12		CONNECTOR F.	
Z1		FILTER	