













# CM 650

## Fahrzeug Diagnose

<p>Service PC</p> 	<p>Hako Diagnose Aktuelle verwenden</p> 	<p>Sontheim Interface Can USB ET-Nr. 03501750</p> 	<p>Rotes Hako Kabel ET-Nr. 03501900</p> 	
<p>alternativ</p>	<p>Service PC</p> 	<p>Hako Diagnose Aktuelle verwenden</p> 	<p>Sontheim Interface Can USB ET-Nr. 03501750</p> 	<p>Hako Diagnosekabel OBD 2 CAN 1 (rot) mit Adapter ET-Nr. 03502750</p> 
<p>alternativ</p>	<p>Service PC</p> 	<p>Hako Diagnose Aktuelle verwenden</p> 	<p>Sontheim Interface Can FOX ET-Nr. 03502430</p> 	<p>Hako Diagnosekabel OBD 2 CAN 1 (rot) ET-Nr. 03502750</p> 

## Motor Diagnose

<p>Service PC</p> 	<p>Diagnose YANMAR Pos. 03503170</p> 	 <p>Lizenz für/for Yanmar Motordiagnose</p>	<p>Yanmar Interface, Hako Ersatzteilnummer 03503170</p> 
---	--	---	---

