



Citymaster 1650 1491.15

9.0.1.2 Hatz Engine Fuelsystem



Citymaster 1650 1491.15

9.0.1.2 Hatz Engine Fuelsystem



1. Leak oil from the injectors
2. Return from the rail to the tank
3. Connection low-pressure conveyor side