

TECHNICAL SERVICE NOTIFICATION

To: Powerboss Dealers

From: PowerBoss Technical Support

Date: 4-1-2013

Subject: Kubota Engine Troubleshooting

Notification:

The new Kubota 1605 LP and Gas engines require software and an E-Comm cable to troubleshoot any Check Engine light issues. The software can be gotten through our Technical Service department and the cable can be ordered through Customer Service. The cable part number is: 600036
The diagnostic/troubleshooting manual is on the Powerboss parts dealer side and can be downloaded.

Models/Serial Numbers Affected:

All units with Kubota 1605 engines regardless of fuel type.

Informational Only For Purchase Warranty