

February 8, 2010

Model: Stealth ASD26BT

An issue with the battery connectors has been noticed in some of the Stealth ASD26BT machines. In some instances it may be difficult to connect the Anderson plugs. If you are experiencing this issue, follow the steps below for a permanent correction.

1. Remove the lugs from the plug by depressing the spring plate and pulling the cable through the back of the plug.



2. Once the plug is removed, wrap the back of the lug with 10-12 layers of electrical tape.



3. Install the lug back into the plug housing. The front of the lug will now sit lower in the housing allowing for easier connection.

