



KUD 2022-07 14.04.2022



Citymaster 1600 / 1650

Extension of system maintenance

Affected vehicles:

Citymaster 1600 1491.01, .02, .12 Citymaster 1650 1491.15

Dear Sir or Madam,

the system maintenance for the affected vehicles has been extended.

The articulated joints must be checked for damage every 1000 operating hours. In addition, the plastic covers on the articulated joints (top + bottom) must be removed and the bearing bushes checked for dirt. In case of contamination, the areas must be cleaned **dry** with a brush.

The necessary documents have already been updated.

Best regards

Jens Grießbach

After Sales Service Hako GmbH

hu

Lars Albermann After Sales Service Hako GmbH