

NEWS

KUD 2020-20
26.11.2020

*Confidential -
For internal use only!*



Citymaster 1650: Coolant level in expansion tank


Affected vehicles: All CM 1650 (1491.15)

Dear Sir or Madam,

In the past few months, we received many reports on the coolant levels of Citymasters 1650 which often are displayed as being too low. Therefore, we adapted the optimal coolant level in the expansion tanks.

When the engine is cool, the coolant level should be about one centimetre **higher than the MAX mark** allows (see figure on the right). There is no need to replace the expansion tank because of this so that warranty claims can no longer be accepted for this purpose.

The operating instructions will be modified accordingly at the next revision.



Please inform your co-workers and customers.

A handwritten signature in blue ink, appearing to read 'André Meier, Lars Albermann', written in a cursive style.

André Meier, Lars Albermann

After Sales Service
Hako GmbH