

## Greg Fisher

---

**From:** Ethan Martin [martin.e@minutemanintl.com]  
**Sent:** Wednesday, June 12, 2013 10:05 AM  
**To:** 'Angie Brown'; 'Greg Fisher'; 'Donna Garner'  
**Cc:** thompson.g@minutemanintl.com  
**Subject:** RE: LP TANK WILL NOT FIT


Greg,

Please see the work instructions below. The rear plate does not need to be flipped. The silver block and anti-rotate device in the rear do need to be removed, but the dark grey plate they are mounted to stays as is.

MODEL: WC-09 HAKOMATIC  
DOCUMENTED BY: John Mye  
PAGE NUMBER: 54  
DATE: 11/21/08

Get (1) WELD-CLAMP LPG MNT. (3342733), (1) WELD-LPG MNT FRT (3342732), (1) SPACER-LPG CAGE (3341113) and (1) CLAMP SCREW-LPG (3341116) and assemble as shown at right.

Core 50 & 5550 LPG Units Only



Close valve on LP tank. Disconnect LP tank hose from LP tank and remove LP tank from unit.

Parts: 3400036 / 3400384 / 3342733  
3342732 / 3341113 / 3341116

Tools: 1/2" Socket / Extension  
Air Ratchet

Place assembly on end of ASSY-LPG TAN in WELD-LPG MNT FRT with holes in CRADDLE. Get (4) SCR-HEX, 5/16-18x WASHER-CONICAL SPRING 5/16 (340 insert though (4) holes, (2) on each side of into (4) weld-nuts on end of ASSY-LPG T Tighten. Replace LP tank in compartment

-Ethan

Ethan W. Martin  
Senior Engineer  
PowerBoss, Inc.  
175 Anderson Street  
Aberdeen, NC 28315  
910.684.4452

The information contained in this transmission is privileged and/or confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message

-----Original Message-----

From: Angie Brown [mailto:brown.a@minutemanimtl.com]  
Sent: Wednesday, June 12, 2013 11:00 AM  
To: 'Greg Fisher'; 'Donna Garner'  
Cc: 'Ethan Martin'; thompson.g@minutemanimtl.com  
Subject: FW: LP TANK WILL NOT FIT

Greg

Ethan has found the correct lock for the LP bottle and no the CORE 50 machine does not get a door(only Hako), please send Donna the information she will need to ship today?

Donna

I will bring you the part, please ship today.

Thanks  
Angie

-----Original Message-----

From: Greg Fisher [mailto:fisher.g@minutemanimtl.com]  
Sent: Wednesday, June 12, 2013 8:48 AM  
To: 'Ethan Martin'  
Cc: 'Angie Brown'; 'Jason Sweet'  
Subject: FW: LP TANK WILL NOT FIT

Ethan,

I know it's early, but do you have an answer to this? Part I understand to reverse the rear plate and remove the block, but what about the door thing?

I'm beginning to wonder if the door was never there on the original "War Pony" "5550" and it was only added for Hako and the 1800. And it was just a pin that kept the bottle from sliding out.

Let me know when you can.

Thanks in advance.

Greg

Greg Fisher

Technical Support Specialist  
Scrubbers and Sweepers  
Minuteman International  
Parts & Service  
14N845 US Rt. 20, Pingree Grove, IL 60140  
www.PowerBossEquipment.com  
Office 800-323-9420 x-2500 Option #3  
Direct: 630-570-2365

Fax: 800-422-6933

The information contained in this transmission is privileged and/or confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message. Thank you

-----Original Message-----

From: Ken Mcneal [mailto:KMcneal@marcoequip.com]  
Sent: Tuesday, June 11, 2013 4:00 PM  
To: Greg Fisher  
Subject: RE: LP TANK WILL NOT FIT

Greg  
Talking to my LP tank vendor all 33lb LP tanks from all manufactures are the same in length . To buy one that would fit in the LP compartment as it is would be a 20 lb LP tank. Which I have been dealing with the customer That we will be delivering this unit to and he will go thur the roof and will be calling every one and their brother.  
You can forward this message as well so they can get ready for the calls too.

Thank you,  
Ken McNeal  
Parts Manager  
909-594-9493, ext. 306  
909-594-9631 fax  
kmcneal@marcoequip.com  
www.marcoequip.com

-----Original Message-----

From: Greg Fisher [mailto:fisher.g@minutemanintl.com]  
Sent: Tuesday, June 11, 2013 8:58 AM  
To: Ken Mcneal  
Subject: RE: LP TANK WILL NOT FIT

Ken,  
I did contact the parties that can help with this first thing this morning. Waiting for a reply.  
I did also just forward your picture.  
Thanks,  
Greg

Greg Fisher

Technical Support Specialist  
Scrubbers and Sweepers  
Minuteman International  
Parts & Service  
14N845 US Rt. 20, Pingree Grove, IL 60140

www.PowerBossEquipment.com  
Office 800-323-9420 x-2500 Option #3  
Direct: 630-570-2365

Fax: 800-422-6933

The information contained in this transmission is privileged and/or confidential information intended for the use of the individual or entity named above. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you are not the intended recipient, please contact the sender by reply email and destroy all copies of the original message. Thank you

-----Original Message-----

From: Ken Mcneal [mailto:KMcneal@marcoequipment.com]  
Sent: Tuesday, June 11, 2013 10:54 AM  
To: fisher.g@minutemanintl.com  
Subject: FW: LP TANK WILL NOT FIT

CORE-50 SERIAL # 19919053

Thank you,  
Ken McNeal  
Parts Manager  
909-594-9493, ext. 306  
909-594-9631 fax  
kmcneal@marcoequipment.com  
www.marcoequipment.com

-----Original Message-----

From: Rick Brown  
Sent: Monday, June 10, 2013 1:50 PM  
To: Ken Mcneal  
Subject: LP TANK WILL NOT FIT