

Side Brooms on a 2020 & up Scrubmaster B175R

Verify the following is set correctly in the Machine Configuration Menu

0.2.7 (Cylindrical Deck)

1.8.1 (Side Broom)

F.0.1 (-A01 Pre-Sweep)

Test the following with Multi-Meter

Test between A01.X15.10 & A01.X15.22 (Resistance between 0.0 to 0.5 OHMs)

Verify same readings at X52 connector between pins 2 & 5

Verify same readings at X45 connector between pins 4 & 8

Test between A01.X11.3 & A01.X11.6 (36VDC)

Verify same readings at X52 connector between pins 1 & 4

Verify same readings at X45 connector between pins 1 & 2

Verify same readings at X45 connector between pins 5 & 6