

Assembly Manual

Transport tool SCM B5 (7150.74)

With regard to handling and operation, also observe the general safety instructions of the corresponding machine in the relevant operating manual.

Valid as from: January 2024

1 Parts list

	Material	Quantity
1	Transport tool SCM B5	1

To fit the transport tool, the Quick-Connect system option (7182.55) is also required for the B260 R and the Quick-Connect system option (7192.30) for the B400 R!

2 Montage



Fig. 1

1. Park the machine on a level surface and switch it off.
2. Hook the transport tool into the Quick-Connect system as shown in **Fig. 1-1**.
3. Pull the rubber band off the ball head **Fig. 1-2** and swivel the clamp **Fig. 1-3** to the side.
4. Place the B5 on the platform as shown in **Fig. 1-4**.
5. Swivel the clamp back and close it with the rubber band **Fig. 1-5**.
6. If required, the battery **Fig. 1-6** and brushes or pads **Fig. 1-7** can be stored in the compartments provided.