



KS 45 E

WIRING DIAGRAM	
A	Switch
B	Horn push button
C	Filter shaker push button
D	Dry charge battery indicator 24V
E	Electric filter shaker
F	Horn
G	Safety switch *
H	Electromagnetic switch 100A
L	Electric engine 24V
M	Negative pole
N	Clamps
P	Steel connector
Q	Mobile connector
R	Battery 24V
S	Fuse 100A
T	Fuse 16A
U	Intermittent lamp
V	Microswitch
Z	Diode 3A

\* OPTIONAL