

## TECHNICAL SERVICE BULLETIN


---

To: [Distributor/Customer]

From: PowerBoss Technical Support

Date: 9/14/2022

Subject: Repair/Replacement of Diode or Capacitor Horn circuit on X3 Harness for ALL Scrubmaster B175R and B260R series scrubbers.



### **Reason for Change**

When horn or horn circuit is shorted out, diode or capacitor will short out requiring complete X3 Main Machine Harness replacement. In lieu of replacing complete harness, Kit #K-260685 allows in the field easy repair of this circuit.

### **Improvement**

Kit #K-260685 allows a horn circuit repair kit to be easily installed in the X3 Main Machine Harness.

---

### **Models/Serial Numbers Affected**

ALL Scrubmater B175R and B260R series

### **Reference Kit Instructions** – For Installation Procedure

#999111

Informational Only    For Purchase    Warranty    Product Improvement

**For further assistance, questions, or comments contact Technical Support at 800-323-9420 (USA)**