

This diagram shows an exploded view of a mechanical assembly. The components are labeled with numbers: 2, 67, 69, 70, 73, 78, 79, 83, 89, 90, 96, 98, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 116, 117, 119, 122, 123, 124, 125, 126, 127, 128, 130, 131, 132, 133, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 155, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200. The assembly includes a base plate (144), a central housing (142), and various internal components like gears (101, 102), springs (105), and a motor (133). The diagram is labeled 'H' at the bottom.

H