

## Release Notes

### Filename:

Diagmaster\_DataBase\_24.01.01.00\_for\_Nonself.exe

### Improvements/Enhancements of this version:

- Addition of the model to support.

## Supported Engines

### V38, V1505CRS and 07 series

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
6047	V3800DICR-TI-E3B-YB1	OEM	V3800	DGM600MK-P	Japan	-	1H0406995	T3	NONE	4.3.0
6048	V3800DICR-TI-E3B-YB2	OEM	V3800	DGM600	Japan	-	1H2486995	T3	NONE	4.3.0
6054	V3800DICR-TE3B-CRMO1	OEM	V3800	CRMO1	Japan	-	1H0316995	T3	NONE	4.3.0
6055	V3800DICR-TIE3B-HN1	OEM	V3800	HN1	Japan	-	1H6806995	T3	NONE	4.3.0
6056	V3800DICR-TI-E3B-DE1	OEM	V3800	DE1	Japan	-	1H6856995	T3	NONE	4.3.0
6057	V3800DICR-TI-E3B-DE2/DE3	OEM	V3800	DE2	Japan	-	1H8036995	T3	NONE	4.3.0
6058	V3800DICR-TI-E3B-NS1	OEM	V3800	NES60TKL	-	-	1H8306995	T3	NONE	4.1.2
6107	V3800-CR-TE4CB-VMR-1/1R	OEM	V3800	D20x22	-	-	1H1816995	T4	DPF	3.3.1
6109	V3800-CR-TE4B-BMG-1	OEM	V3800	TE4B-BMG-1	-	-	1H1646995	T4	DPF	4.3.0
6110	V3800-CR-TE4B-DCI-1	OEM	V3800	TE4B-DCI-1	-	-	1H1636995	T4	DPF	4.3.0
6112	V3800-CR-TE4B-EPS-1	OEM	V3800	TE4B-EPS-1	-	-	1H1656995	T4	DPF	4.3.0
6113	V3800-CR-TE4B-MRO-1	OEM	V3800	TE4B-MRO-1	-	-	1H1666995	T4	DPF	4.3.0
6114	V3800-CR-TE4B-MRO-2	OEM	V3800	TE4B-MRO-2	-	-	1H1676995	T4	DPF	4.3.0
6127	V3800-CR-TIE4B-BGHE1	OEM	V3800	TIE4B-BGHE1	-	-	1H7266995	T4	DPF	4.3.0
6129	V3800-CR-TIE4B-DCI-1	OEM	V3800	TIE4B-DCI-1	-	-	1H1106995	T4	DPF	4.3.0
6130	V3800-CR-TIE4B-BMG-1	OEM	V3800	TIE4B-BMG-1	-	-	1H1116995	T4	DPF	4.3.0
6131	V3800-CR-TE4B-EPS-2	OEM	V3800	TE4B-EPS-2	-	-	1H1686995	T4	DPF	4.3.0
6132	V3800-CR-TE4B-AFHN1/2	OEM	V3800	TE4B-AFHN1/2	-	-	1H7016995	T4	DPF	4.3.0
6137	V3800-CR-TE4B-RRSH1	OEM	V3800	TE4B-RRSH1	-	-	1H1846995	T4	DPF	4.3.0
6138	V3800-CR-TIE4B-RRSH1	OEM	V3800	TIE4B-RRSH1	-	-	1H1236995	T4	DPF	4.3.0
6144	V3800-CR-TIE4B-AUS-1	OEM	V3800	TIE4B-AUS-1	-	-	1H1136995	T4	DPF	4.3.0
6149	V3800-CR-TIE4CB-KSR1	OEM	V3800	N115	Europe	-	1H1126995	T4	DPF	4.3.0
6150	V3800-CR-TE4B-DCI-2	OEM	V3800	TE4B-DCI-2	-	-	1H1696995	T4	DPF	4.3.0
6151	V3800-CR-TIE4B-DCI-2	OEM	V3800	TIE4B-DCI-2	-	-	1H1146995	T4	DPF	4.3.0
6153	V3800-CR-TE4B-MAT-1	OEM	V3800	TE4B-MAT-1	-	-	1H7026995	T4	DPF	4.3.0
6155	V3800-CR-TE4B-CRMO1	OEM	V3800	MST-700VDL	Japan	-	1H1866995	T4	DPF	4.1.2
6158	V3800-CR-TE4B-RRSH2	OEM	V3800	MW703	-	-	1H1886995	T4	DPF	4.1.5
6159	V3800-CR-TE4B-HOF-1	OEM	V3800	H33-4	-	-	1H0576997	T4	DPF	4.1.5
6161	V3800-CR-TE4B-EPS-3	OEM	V3800	TE4B-EPS-3	-	-	1H7036995	T4	DPF	4.1.5
6162	V3800-CR-TE4B-ANT-S1	OEM	V3800	TE4B-ANT-S1	-	-	1H0656997	T4	DPF	4.1.5
6165	V3800-CR-TE4B-BCS-S1	OEM	V3800	TE4B-BCS-S1	-	-	1H0826997	T4	DPF	4.2.0
6166	V3800-CR-TIE4B-ITC-1/2/3	OEM	V3800	TIE4B-ITC-1	Italy	-	1H1156995	T4	DPF	4.2.0
6171	V3800-CR-TE4B-ANT-1	OEM	V3800	TGF 10900	-	-	1H0986997	T4	DPF	4.2.2
6172	V3800-CR-TE4B-BCS-1	OEM	V3800	Volcan V950AR	-	-	1H0996997	T4	DPF	4.2.2
6173	V3800-CR-TE4B-SSMR1	OEM	V3800	BSA3000	-	-	1H0036997	T4	DPF	4.2.2
6175	V3800-CR-TIE4B-CRIF1	OEM	V3800	U-4D	-	-	1H1246995	T4	DPF	4.2.3
6180	V3800-CR-TE4B-RRSH3	OEM	V3800	TZ704	-	-	1H7046995	T4	DPF	4.2.7
6181	V3800-CR-TE4B-BHIF1	OEM	V3800	CT-500	Japan	-	1H1896995	T4	DPF	4.2.8
6182	V3800-CR-TE4B-ANT-2	OEM	V3800	TGF9000	-	-	1H2216995	T4	DPF	4.2.9
6187	V3800-CR-TE4B-ANT-3	OEM	V3800	TGF7900	-	-	1H2386997	T4	DPF	4.2.10
6188	V3800-CR-TE4B-AFHN3	OEM	V3800	F45C5	Japan	-	1H7056995	T4	DPF	4.2.16
6189	V3800-CR-TE4B-HMCH1	OEM	V3800	CG750	-	-	1H7066995	T4	DPF	4.2.17
6215	V3800-CR-TE4B-CSPB-1	OEM	V3800	CR-TE4B-CSPB-1	-	-	1H6136998	T4	DPF	22.11.01
6217	V3800-CR-TIE4B-ZML-1	OEM	V3800	CR-TIE4B-ZML-1	-	-	1H5936998	T4	DPF	23.03.01
6220	V3800-CR-TE4B-SWD2-1	OEM	V3800	CR-TE4B-SWD2-1	-	-	1H6566998	T4	DPF	23.07.01
6222	V3800-CR-TIE4B-HE2-1	OEM	V3800	CR-TIE4B-HE2-1	-	-	1H5836998	T4	DPF	23.10.01
6223	V3800-CR-TIE2-CTB1	OEM	V3800	DC-120X	Thai,Laos,Cambodia	-	1H2206998	T2	NONE	23.11.01
6401	V3800DICR-TIE3B-ACC1	OEM	V3800	TIE3B-ACC1	-	-	1H6856995	T3	NONE	4.2.2
6402	V3800DICR-TI-E3B-DE4	OEM	V3800	DIS-80VPB	-	-	1H1816997	T3	NONE	4.2.4
6414	V3800DICR-TI-E3B-DE5	OEM	V3800	DCA-60LSKE-D2	-	-	1H6496997	T3	NONE	4.3.10
6503	V3800DICR-TIE3B-HE1	OEM	V3800	PDS400	-	-	1H0896997	T3(E4)	NONE	4.2.1
6505	V3800-CR-TE3B-MAT-1	OEM	V3800	Azura MC 210	-	-	1H0636997	T3(E4)	NONE	4.2.3
6512	V3800DICR-TIE3B-HE-2	OEM	V3800	TIE3B-HE-2	-	-	1H1746998	T3	NONE	21.1.25
6513	V3800DICR-TIE3B-SH1	OEM	V3800	V3800DICR-TIE3B-SH1	-	-	1H8806998	T3(E4)	NONE	21.12.02
6704	V1505-CR-TE5B-ACP-1	OEM	V1505CRS	XAS88	-	-	1H6196997	T5	DPF	19.12.16
6705	V1505-CR-TE5B-RNS-1	OEM	V1505CRS	Fairway305/405	-	-	1H6216997	T5	DPF	20.8.6
6706	V1505-CR-TE5B-EU-Z1	OEM	V1505CRS	TE5B-EU-Z1	-	-	1H6206997	T5	DPF	20.8.6
6707	V1505-CR-TE5B-LMKY-1	OEM	V1505CRS	LM551B	-	-	1H6226997	T5	DPF	20.8.6
6708	V1505-CR-TE5B-RIO-1	OEM	V1505	Sweepers City Jet	-	-	1H6236997	T5	DPF	20.11.30
6709	V1505-CR-TE5B-SEE-1	OEM	V1505	Wood Chipper	-	-	1H6246997	T5	DPF	20.11.30
6712	V1505-CR-TE5B-PES-1	OEM	V1505CRS	TE5B-PES-1	-	-	1H6256997	T5	DPF	21.1.25
6713	V1505-CR-TE5B-COM-1	OEM	V1505	CR-TE5B-COM-1	-	-	1H1276998	T5	DPF	21.2.1
6714	V1505-CR-TE5B-MAC-1	OEM	V1505	TE5B-MAC-1	-	-	1H6266997	T5	DPF	21.2.1
6716	V1505-CR-TE5B-CMG-1	OEM	V1505CRS	CR-TE5B-CMG-1	-	-	1H1286998	T5	DPF	21.4.1
6718	V1505-CR-TE5B-SSSU-1	OEM	V1505CRS	CR-TE5B-SSSU-1	-	-	1H6386997	T5	DPF	21.09.01
6719	V1505-CR-TE5B-AVN-1	OEM	V1505CRS	CR-TE5B-AVN-1	-	-	1H1296998	T5	DPF	21.12.01
6723	V1505-CR-TE5B-KEA-1	OEM	V1505CRS	CR-TE5B-KEA-1	-	-	1H1306998	T5	DPF	22.04.01
6724	V1505-CR-TE5B-ERM-1	OEM	V1505CRS	CR-TE5B-ERM-1	-	-	1H1316998	T5	DPF	22.04.01
6725	V1505-CR-TE5B-DSV-1	OEM	V1505CRS	CR-TE5B-DSV-1	-	-	1H1326998	T5	DPF	22.05.01
6730	V1505-CR-TE5B-GEO-1	OEM	V1505CRS	CR-TE5B-GEO-1	-	-	1H0216898	T5	DPF	22.07.01
6731	V1505-CR-TE5B-SEE-2	OEM	V1505CRS	CR-TE5B-SEE-2	-	-	1H1336998	T5	DPF	22.12.01
6732	V1505-CR-TE5B-BRO-1	OEM	V1505CRS	CR-TE5B-BRO-1	-	-	1H1346998	T5	DPF	23.08.01
6733	V1505-CR-TE5B-EUZ1-2	OEM	V1505CRS	CR-TE5B-EUZ1-2	-	-	1H5426898	T5	DPF	23.08.01
6734	V1505-CR-TE5B-JSQ-1	OEM	V1505CRS	CR-TE5B-JSQ-1	-	-	1H5436898	T5	DPF	24.01.01
7022	V3307-CR-TE4B-BMG-1	OEM	V3307	TE4B-BMG-1	-	-	1H2726995	T4	DPF	4.3.0

★ addition

7023	V3307-CR-TE4B-DYP-1	OEM	V3307	TE4B-DYP-1	-	-	1H2806995	T4	DPF	4.3.0
7024	V3307-CR-T-E4B-BMG-2	OEM	V3307	TE4B-BMG-2	-	-	1H2736995	T4	DPF	4.3.0
7028	V3307-CR-TE4B-DCI-1	OEM	V3307	TE4B-DCI-1	-	-	1H2556995	T4	DPF	4.3.0
7029	V2607-CR-TE4B-AEB-1	OEM	V2607	TE4B-AEB-1	-	-	1H3026995	T4	DPF	4.3.0
7036	V3307-CR-TE4B-HAM-1	OEM	V3307	TE4B-HAM-1	-	-	1H2826995	T4	DPF	4.3.0
7037	V3307-CR-TE4B-HAM-2	OEM	V3307	TE4B-HAM-2	-	-	1H2836995	T4	DPF	4.3.0
7038	V2607-CR-TE4B-BRG-1	OEM	V2607	TE4B-BRG-1	-	-	1H3036995	T4	DPF	4.3.0
7039	V3307-CR-TE4B-AIE-1	OEM	V3307	TE4B-AIE-1	-	-	1H2746995	T4	DPF	4.3.0
7043	V3307-CR-TE4B-RRSH1/RRSH2	OEM	V3307	R2-4	-	-	1H2856995	T4	DPF	4.1.1
7044	V3307-CR-TE4B-TCKH1	OEM	V3307	MS-32	-	-	1H2566995	T4	DPF	4.1.1
7049	V2607-CR-TE4B-DMD-1	OEM	V2607	TE4B-DMD-1	-	-	1H3056995	T4	DPF	4.1.2
7050	V2607-CR-TE4B-EPS-1	OEM	V2607	TE4B-EPS-1	-	-	1H3046995	T4	DPF	4.1.2
7053	V3307-CR-TE4B-KSR-1	OEM	V3307	M78	-	-	1H2756995	T4	DPF	4.1.2
7057	V2607-CR-TE4B-BHMK1	OEM	V2607	TE4B-BHMK1	-	-	1H3226995	T4	DPF	4.1.5
7059	V2607-CR-TE4B-HLD-1	OEM	V2607	C270	-	-	1H3126995	T4	DPF	4.1.5
7060	V3307-CR-TE4B-EU-Z5	OEM	V3307	TE4B-EU-Z5	-	-	1H2766995	T4	DPF	4.1.5
7064	V3307-CR-TE4B-DMD-1	OEM	V3307	CC7574	-	-	1H2496995	T4	DPF	4.2.1
7065	V3307-CR-TE4B-EPI-1	OEM	V3307	PP 4500	-	-	1H2776995	T4	DPF	4.2.2
7066	V3307-CR-TE4B-RRSH3	OEM	V3307	SV204	-	-	1H2866995	T4	DPF	4.2.2
7072	V3307-CR-TE4B-DWC-1	OEM	V3307	JT 20	-	-	1H2516995	T4	DPF	4.2.4
7075	V2607-CR-TE4B-DWC-1	OEM	V2607	JT10	-	-	1H3136995	T4	DPF	4.2.8
7077	V2607-CR-TE4B-AEB-1	OEM	V2607	TE4B-AEB-1	-	-	1H3066995	T4	DPF	4.2.9
7078	V2607-CR-TE4B-BRG-1	OEM	V2607	TE4B-BRG-1	-	-	1H3076995	T4	DPF	4.2.9
7079	V2607-CR-TE4B-DMD-1	OEM	V2607	TE4B-DMD-1	-	-	1H2066997	T4	DPF	4.2.9
7080	V2607-CR-TE4B-EPS-1	OEM	V2607	TE4B-EPS-1	-	-	1H2056997	T4	DPF	4.2.9
7081	V3307-CR-TE4B-DWC-2	OEM	V3307	HX75	-	-	1H2376997	T4	DPF	4.2.10
7082	V3307-CR-TE4B-DCI-2	OEM	V3307	Agri Pivot T60	-	-	1H1016997	T4	DPF	4.2.11
7086	V3307-CR-TE4B-BRO-1	OEM	V3307	Giant+50	-	-	1H2786995	T4	DPF	4.2.12
7090	V3307-CR-TE4B-AMN-1	OEM	V3307	ARS70	-	-	1H2876995	T4	DPF	4.2.12
7092	V2607-CR-TE4B-ITC-1	OEM	V2607	TE4B-ITC-1	-	-	1H3086995	T4	DPF	4.3.2
7105	V2607-CR-TE4B-EPS-2	OEM	V2607	CR-TE4B-EPS-2	-	-	1H4816898	T4	DPF	23.01.01
7505	V3307-CR-TIE4B-MRO-1	OEM	V3307	P.27.6	-	-	1H8516995	T4	DOC	4.2.1
7509	V2607-CR-TIE4B-HLT-1	OEM	V2607	H28RTJ	-	-	1H1836997	T4	DOC	4.2.4
7511	V3307-CR-TIE4B-BRC-1	OEM	V3307	KR-350	-	-	1H2286997	T4	DOC	4.2.8
7512	V3307-CR-TIE4B-KEA-1	OEM	V3307	TIE4B-KEA-1	-	-	1H8526995	T4	DOC	4.2.10
7513	V2607-CR-TIE4B-XCM-1	OEM	V2607	XE75U	-	-	1H8406995	T4	DOC	4.2.12
7514	V3307-CR-TIE4B-BDS-1	OEM	V3307	TIE4B-BDS-1	-	-	1H6126997	T4	DOC	4.3.5
7515	V3307-CR-TIE4B-MRO-1	OEM	V3307	P.27.6	-	-	1H6606997	T4	DOC	19.10.17
7516	V2607-CR-TIE4B-SNY-1	OEM	V2607	TIE4B-SNY-1	-	-	1H8396995	T4	DOC	20.8.6
7520	V3307-TIE4AB-KEA-1	OEM	V3307	TIE4AB-KEA-1	-	-	1H8796998	T4	DOC	21.12.02
7521	V3307-CR-TIE4B-KEA-1	OEM	V3307	CR-TIE4B-KEA-1	-	-	1H4776898	T4	DOC	23.01.01
7709	V2607-CR-TE5B-HLD-1	OEM	V2607	TE5B-HLD-1	-	-	1H3576997	T5	DPF	4.3.3
7710	V3307-CR-TE5B-BMG-1	OEM	V3307	TE5B-BMG-1	-	-	1H3386997	T5	DPF	4.3.3
7711	V3307-CR-TE5B-BMG-2	OEM	V3307	TE5B-BMG-2	-	-	1H3396997	T5	DPF	4.3.3
7713	V3307-CR-TE5B-HAM-2	OEM	V3307	TE5B-HAM-2	-	-	1H4086997	T5	DPF	4.3.3
7715	V3307-CR-TE5B-HAM-1	OEM	V3307	TE5B-HAM-1	-	-	1H4076997	T5	DPF	4.3.3
7716	V3307-CR-TE5B-KSR-1	OEM	V3307	TE5B-KSR-1	-	-	1H3406997	T5	DPF	4.3.3
7717	V3307-CR-TE5B-AMN-1	OEM	V3307	TE5B-AMN-1	-	-	1H3456997	T5	DPF	4.3.3
7722	V2607-CR-TE5B-AEB-1	OEM	V2607	TE5B-AEB-1	-	-	1H3546997	T5	DPF	4.3.3
7723	V3307-CR-TE5B-DYP-1	OEM	V3307	CA1400	-	-	1H4096997	T5	DPF	4.3.3
7724	V2607-CR-TE5B-HLT-1	OEM	V2607	HT28RTJ	-	-	1H3556997	T5	DPF	4.3.4
7725	V3307-CR-TE5B-BRO-1	OEM	V3307	WL	-	-	1H3376997	T5	DPF	4.3.4
7727	V3307-CR-TE5B-EU-Z5	OEM	V3307	TE5B-EU-Z5	-	-	1H6036997	T5	DPF	4.3.4
7728	V3307-CR-TE5B-DCI-2	OEM	V3307	TE5B-DCI-2	-	-	1H5106997	T5	DPF	4.3.4
7731	V3307-CR-TE5B-DCI-1	OEM	V3307	TE5B-DCI-1	-	-	1H5096997	T5	DPF	4.3.4
7741	V2607-CR-TE5B-HDM-1	OEM	V2607	HMK60CR	-	-	1H3626997	T5	DPF	4.3.5
7742	V2607-CR-TE5B-EU-Z8	OEM	V2607	TE5B-EU-Z8	-	-	1H3536997	T5	DPF	4.3.5
7743	V2607-CR-TE5B-SMP-1	OEM	V2607	TE5B-SMP-1	-	-	1H6486997	T5	DPF	4.3.5
7744	V3307-CR-TE5B-SWD-1	OEM	V3307	SWL3230F	-	-	1H5136997	T5	DPF	4.3.5
7745	V3307-CR-TE5B-SMR-1	OEM	V3307	S-22EZ	-	-	1H5126997	T5	DPF	4.3.5
7747	V3307-CR-TE5B-AEB-1	OEM	V3307	P48P	-	-	1H6656997	T5	DPF	4.3.7
7748	V2607-CR-TE5B-BRG-1	OEM	V2607	Dumper X2	-	-	1H6646997	T5	DPF	4.3.7
7750	V2607-CR-E5B-HLD-1	OEM	V2607	C55	-	-	1H3736997	T5	DPF	4.3.9
7751	V2607-CR-TE5B-CIE-1	OEM	V2607	Apollo GEN2	-	-	1H6786997	T5	DPF	4.3.11
7754	V2607-CR-TE5B-SMP-2	OEM	V2607	G0ZT	-	-	1H7576997	T5	DPF	4.3.9
7755	V2607-CR-TE5B-SMP-3	OEM	V2607	ETL180	-	-	1H7586997	T5	DPF	4.3.9
7758	V2607-CR-E5B-AEB-1	OEM	V2607	TT206	-	-	1H3746997	T5	DPF	4.3.12
7759	V2607-CR-E5B-EU-Z8	OEM	V2607	E5B-EU-Z8	-	-	1H9356997	T5	DPF	19.11.15
7760	V3307-CR-TIE5B-DCI-1	OEM	V3307	Zeus 35.11	-	-	1H2976997	T5	DPF	19.11.15
7761	V2607-CR-E5B-HCF-1	OEM	V2607	CPCD35-XW97F	-	-	1H3766997	T5	DPF	19.11.15
7762	V2607-CR-E5B-HCF-2	OEM	V2607	CPCD35-MW97B	-	-	1H3776997	T5	DPF	19.11.15
7764	V2607-CR-TE5B-SWD-1	OEM	V2607	SWE60UF	-	-	1H3926997	T5	DPF	19.11.15
7765	V2607-CR-TE5B-HCF-1	OEM	V2607	CPCD35-XW98C-RT4	-	-	1H3586997	T5	DPF	19.12.16
7767	V3307-CR-TIE5B-HCF-1	OEM	V3307	CPCD50	-	-	1H3056997	T5	DPF	19.12.16
7768	V3307-CR-TE5B-KEA-1	OEM	V3307	TE5B-KEA-1	-	-	1H0166998	T5	DPF	20.1.20
7769	V3307-CR-TE5B-DWC-1	OEM	V3307	HX75	-	-	1H0156998	T5	DPF	20.1.20
7776	V3307-CR-TE5B-CRMO1	OEM	V3307	MST-700VDR	-	-	1H0206998	T5	DPF	20.3.20
7784	V2607-CR-TE5B-BRG-2	OEM	V2607	C805	-	-	1H1226998	T5	DPF	20.11.30
7786	V2607-CR-E5B-HCF-1	OEM	V2607	CPCD35-XW97F	-	-	1H1786998	T5	DPF	20.12.28
7787	V2607-CR-E5B-HCF-2	OEM	V2607	CPCD35-MW97B	-	-	1H1796998	T5	DPF	20.12.28
7788	V2607-CR-E5B-AEB-1	OEM	V2607	TT206	-	-	1H1806998	T5	DPF	20.12.28
7789	V2607-CR-E5B-HLD-1	OEM	V2607	C55	-	-	1H1816998	T5	DPF	20.12.28
7790	V2607-CR-E5B-EU-Z8	OEM	V2607	E5B-EU-Z8	-	-	1H1826998	T5	DPF	20.12.28
7795	V3307-CR-TE5B-HYL-1	OEM	V3307	Easy Tum 113A	-	-	1H1676998	T5	DPF	20.12.28
7796	V3307-CR-TIE5B-TFT-1	OEM	V3307	PLUS2 4-5T	-	-	1H1626998	T5	DPF	20.12.28
7797	V2607-CR-TE5B-XCM-1	OEM	V2607	CR-TE5B-XCM-1	-	-	1H2136998	T5	DPF	21.3.1
7798	V2607-CR-TE5B-HCF-2	OEM	V2607	CR-TIE5B-HCF-2	-	-	1H2106998	T5	DPF	21.4.1
7799	V3307-CR-TE5B-XCM-1	OEM	V3307	CR-TE5B-XCM-1	-	-	1H2226998	T5	DPF	21.4.1
7803	V2607-CR-TE5B-SMR-1	OEM	V2607	CR-TE5B-SMR-1	-	-	1H3076998	T5	DPF	21.06.01
7804	V2607-CR-TE5B-HDM-2	OEM	V2607	CR-TE5B-HDM-2	-	-	1H3636997	T5	DPF	21.06.01
7805	V3307-CR-TE5B-DMD-1	OEM	V3307	CR-TE5B-DMD-1	-	-	1H3726998	T5	DPF	21.06.01
7806	V3307-CR-TIE5B-DCI-2	OEM	V3307	CR-TIE5B-DCI-2	-	-	1H2986997	T5	DPF	21.08.01
7807	V3307-CR-TE5B-HAM-1	OEM	V3307	CR-TE5B-HAM-1	-	-	1H4106997	T5	DPF	21.08.01
7808	V3307-CR-TE5B-HAM-2	OEM	V3307	CR-TE5B-HAM-2	-	-	1H4116997	T5	DPF	21.08.01
7809	V3307-CR-TE5B-AMN-1	OEM	V3307	CR-TE5B-AMN-1	-	-	1H6686998	T5	DPF	21.08.01
7810	V3307-CR-TE5B-DYP-1	OEM	V3307	CR-TE5B-DYP-1	-	-	1H6696998	T5	DPF	21.08.01
7811	V3307-CR-TE5B-XCM-1	OEM	V3307	CR-TE5B-XCM-1	-	-	1H6436998	T5	DPF	21.10.01
7815	V2607-CR-TIE5B-ZML-1	OEM	V2607	ZT26J	-	-	1H6856998	T5	DPF	21.10.01
7817	V3307-TE5AB-BMG-3	OEM	V3307	TE5AB-BMG-3	-	-	1H0566998	T5	DPF	21.12.01
7818	V3307-TE5AB-HAM-3/V3307-TE5AB-HAM-4	OEM	V3307	h5/h7	-	-	1H0616998	T5	DPF	21.12.01
7819	V3307-CR-TE5B-STR-1	OEM	V3307	CR-TE5B-STR-1	-	-	1H4116998	T5	DPF	21.12.01
7823	V3307-TE5AB-EU-Z5	OEM	V3307	TE5AB-EU-Z5	-	-	1H0576998	T5	DPF	21.12.02
7826	V2607-CR-E5B-HCF-3	OEM	V2607	CR-E5B-HCF-3	-	-	1H9766998	T5	DPF	21.12.02



18054	V2403-CR-E4B-ACP-1	OEM	V2403E4	XAS185	-	-	1H4856995	T4	DPF	3.3.6
18055	D1803-CR-E4B-TXN-1	OEM	D1803E4	LF550/LF570	-	-	1H5326995	T4	DPF	20.9.14
18062	D1803-CR-E4B-BMG-1	OEM	D1803E4	BW120	-	-	1H5506995	T4	DPF	4.1.0
18063	V2403-CR-TE4B-KEA-1/2	OEM	V2403E4T	TE4B-KEA-1/2	-	North America	1H3766995	T4	DPF	4.1.0
18064	V2403-CR-TE4BG-KEA-1	OEM	V2403E4T	TE4BG-KEA-1	-	North America	1H8286995	T4	DPF	4.1.0
18065	D1803-CR-TE4B-EPS-1	OEM	D1803E4T	TE4B-EPS-1	-	-	1H4546995	T4	DPF	4.1.0
18066	D1803-CR-E4B-EPS-1	OEM	D1803E4	E4B-EPS-1	-	-	1H5336995	T4	DPF	4.1.0
18067	V2403-CR-E4B-BH1H-1	OEM	V2403E4	E4B-BH1H-1	-	-	1H5116995	T4	DPF	4.1.1
18068	D1803-CR-E4B-WKR-1	OEM	D1803E4	RD27	-	-	1H5356995	T4	DPF	4.1.1
18070	V2403-CR-TE4B-RMKY-1	OEM	V2403E4T	GM2810	-	-	1H4326995	T4	DPF	4.1.1
18071	V2403-CR-E4B-AFHN-1	OEM	V2403E4	E4B-AFHN-1	-	-	1H5236995	T4	DPF	4.1.2
18072	V2403-CR-TE4B-SSSU-1	OEM	V2403E4T	TE4B-SSSU-1	-	-	1H3776995	T4	DPF	4.1.2
18073	V2403-CR-E4B-KSR-1	OEM	V2403E4	E4B-KSR-1	-	-	1H4916995	T4	DPF	4.1.2
18074	D1803-CR-TE4B-KEA-1	OEM	D1803E4T	TE4B-KEA-1	-	North America	1H4536995	T4	DPF	4.1.2
18075	D1803-CR-E4B-KEA-1/2	OEM	D1803E4	E4B-KEA-1/2	-	North America	1H5346995	T4	DPF	4.1.2
18076	D1803-CR-TE4B-DYP-1	OEM	D1803E4T	CC1300	-	-	1H4556995	T4	DPF	4.1.2
18077	V2403-CR-E4B-KEA-1	OEM	V2403E4	E4B-KEA-1	-	North America	1H4866995	T4	DPF	4.1.2
18078	V2403-CR-TE4B-GEO-1	OEM	V2403E4T	7822DT/6622CPT	-	-	1H3786995	T4	DPF	4.1.2
18081	V2403-CR-E4B-KSR-2	OEM	V2403E4	M58	-	-	1H0156997	T4	DPF	4.1.4
18082	V2403-CR-E4B-HAM-1	OEM	V2403E4	HD13/14	-	-	1H4876995	T4	DPF	4.1.4
18087	V2403-CR-TE4B-AFHN-1	OEM	V2403E4T	F40W5	-	-	1H4406995	T4	DPF	4.1.4
18090	V2403-CR-TIE4BG-EPS1	OEM	V2403E4TDOC	TIE4BG-EPS1	-	-	1H0026997	T4	DOC	4.1.4
18094	V2403-CR-TE4B-KRC-1	OEM	V2403E4T	MIC70	-	-	1H3796995	T4	DPF	4.1.5
18098	V2403-CR-E4B-BMG-1	OEM	V2403E4	BW138	-	-	1H5146995	T4	DPF	4.1.5
18100	V2403-CR-E4B-SSSU-1	OEM	V2403E4	J3	-	-	1H5136995	T4	DPF	4.1.5
18101	V2403-CR-E4B-SSSU-2	OEM	V2403E4	J2	-	-	1H5156995	T4	DPF	4.1.5
18102	V2403-CR-TIE4B-KEA-1/2/3	OEM	V2403E4TDOC	TIE4B-KEA-1/2/3	-	North America	1H8756995	T4	DOC	4.1.5
18105	D1803-CR-E4B-TPMK-1	OEM	D1803E4	E4B-TPMK-1	-	-	1H5516995	T4	DPF	4.1.5
18107	D1803-CR-E4B-RRBM-1	OEM	D1803E4	KV40CSI	-	-	1H5526995	T4	DPF	4.1.5
18108	D1803-CR-TE4B-SSMR-1	OEM	D1803E4T	TE4B-SSMR-1	-	-	1H4606995	T4	DPF	4.1.5
18109	D1803-CR-TIE4B-KEA-1	OEM	D1803E4TDOC	TIE4B-KEA-1	-	North America	1H0536997	T4	DOC	4.1.5
18111	D1803-CR-TIE4BG-KEA1	OEM	D1803E4TDOC	TIE4BG-KEA1	-	North America	1H0616997	T4	DOC	4.1.5
18112	D1803-CR-E4B-HMKY-1	OEM	D1803E4	HM5500	-	-	1H5366995	T4	DPF	4.1.5
18116	D1803-CR-TIE4BG-EPS1	OEM	D1803E4TDOC	S10020	-	-	1H0016997	T4	DOC	4.1.5
18118	V2403-CR-TIE4BG-PTI1	OEM	V2403E4TDOC	TIE4BG-PTI1	-	-	1H0676997	T4	DOC	4.1.5
18119	V2403-CR-E4B-RFR-1	OEM	V2403E4	Site Max	-	-	1H4926995	T4	DPF	4.1.5
18120	V2403-CR-TE4B-TMC-1	OEM	V2403E4T	SS435	-	-	1H4426995	T4	DPF	4.1.5
18121	D1803-CR-E4B-TRX-1	OEM	D1803E4	X35NA	-	-	1H5606995	T4	DPF	4.1.5
18122	V2403-CR-TIE4BG-MLR1	OEM	V2403E4TDOC	TIE4BG-MLR1	-	-	1H0596997	T4	DOC	4.2.0
18126	D1803-CR-TE4B-SSSU-1	OEM	D1803E4T	Z4	-	-	1H4616995	T4	DPF	4.2.0
18133	D1803-CR-TIE4BG-EPS2	OEM	D1803E4TDOC	C20	-	-	1H0936997	T4	DOC	4.2.1
18134	V2403-CR-TIE4BG-KEA1	OEM	V2403E4TDOC	TIE4BG-KEA1	-	North America	1H0526997	T4	DOC	4.2.1
18136	V2403-CR-TE4B-EU-X8	OEM	V2403E4T	TE4B-EU-X8	-	Europe	1H0966997	T4	DPF	4.2.1
18137	V2403-CR-TE4B-PMS-1	OEM	V2403E4T	Mixokret M760	-	-	1H0956997	T4	DPF	4.2.1
18143	V2403-CR-TIE4B-ASV-1	OEM	V2403E4TDOC	VT65	-	North America	1H1076997	T4	DOC	4.2.2
18144	V2403-CR-E4B-LMKY-1	OEM	V2403E4	LM2710	-	Japan	1H4936995	T4	DPF	4.2.2
18145	V2403-CR-E4B-HLT-2	OEM	V2403E4	HA20RTJ	-	France	1H4886995	T4	DPF	4.2.2
18146	V2403-CR-TE4B-ACP-1	OEM	V2403E4T	XAS 138	-	Belgium	1H1026997	T4	DPF	4.2.2
18147	D1803-CR-TIE4B-BDS-1	OEM	D1803E4TDOC	IC35	-	North America	1H1416997	T4	DOC	4.2.2
18148	D1803-CR-TIE4B-ACP-1	OEM	D1803E4TDOC	XAS 185 Plus	-	North America	1H1426997	T4	DOC	4.2.2
18151	D1803-CR-TIE4B-BDS-2	OEM	D1803E4TDOC	IC20	-	North America	1H1636997	T4	DOC	4.2.2
18152	V2403-CR-TIE4BG-DNY1	OEM	V2403E4TDOC	DCA-40SSKU4F2	-	Japan	1H1286997	T4	DOC	4.2.2
18154	V2403-CR-E4B-EU-X8/XP8	OEM	V2403E4	E4B-EU-X8/XP8	-	Europe	1H1896997	T4	DPF	4.2.3
18155	V2403-CR-E4B-SBFU-1	OEM	V2403E4	SF1248DK3	-	Japan	1H4896995	T4	DPF	4.2.3
18156	D1803-CR-E4B-SSMR-1	OEM	D1803E4	V602C	-	-	1H5546995	T4	DPF	4.2.3
18157	D1803-CR-TE4B-WCOS-1	OEM	D1803E4T	TE4B-WCOS-1	-	-	1H4626995	T4	DPF	4.2.3
18158	V2403-CR-TE4B-EU-XS8	OEM	V2403E4T	TE4B-EU-XS8	-	Europe	1H1826997	T4	DPF	4.2.4
18159	V2403-CR-TIE4B-FLMO1	OEM	V2403E4TDOC	MFD-20	-	Japan	1H8836995	T4	DOC	4.2.4
18160	D1803-CR-E4B-EU-X8/XP8	OEM	D1803E4	E4B-EU-X8/XP8	-	Europe	1H5376995	T4	DPF	4.2.4
18161	D1803-CR-TE4B-EU-X8	OEM	D1803E4T	TE4B-EU-X8	-	Europe	1H4576995	T4	DPF	4.2.4
18163	D1803-CR-TE4B-SSMR-2	OEM	D1803E4T	SSA-alpha1005	-	-	1H4636995	T4	DPF	4.2.8
18164	V2403-CR-E4B-HMCH-1	OEM	V2403E4	E4B-HMCH-1	-	-	1H2306997	T4	DPF	4.2.4
18168	D1803-CR-E4B-SSMR-2	OEM	D1803	SSA-Alpha605	-	-	1H5556995	T4	DPF	4.2.9
18169	V2403-CR-TIE4B-SKL-1	OEM	V2403E4TDOC	TB86J/AB60J	-	-	1H2366997	T4	DOC	4.2.9
18170	D1803-CR-TE4B-SSMR-3	OEM	D1803E4	SSA-F617-01	-	-	1H4646995	T4	DPF	4.2.9
18172	V2403-CR-TIE4B-AIE-1	OEM	V2403E4TDOC	V2403 DOC-PWRU	-	-	1H8786995	T4	DOC	4.2.10
18173	D1803-CR-TE4B-VCE-1	OEM	D1803E4T	DD30/35	-	-	1H4586995	T4	DPF	4.2.10
18174	D1803-CR-TIE4B-AIE-1	OEM	D1803E4TDOC	D1803-T Power Unit	-	-	1H8636995	T4	DOC	4.2.10
18175	V2403-CR-TE4B-KRC-2	OEM	V2403E4T	MC120 Adv plus	-	-	1H2636997	T4	DPF	4.2.10
18177	D1803-CR-E4B-DYP-1	OEM	D1803E4	CC1100/CC1200	-	-	1H5386995	T4	DPF	4.2.10
18178	D1803-CR-TE4B-DWC-1	OEM	D1803E4T	HX50	-	-	1H4596995	T4	DPF	4.2.10
18179	D1803-CR-TIE4B-ASV-1	OEM	D1803E4TDOC	R070T/PT35	-	-	1H2316997	T4	DOC	4.2.10
18182	V2403-CR-TIE4BG-CPG1	OEM	V2403E4	20kW Com. Mobile Genset	-	-	1H2646997	T4	DOC	4.2.11
18184	V2403-CR-TIE4B-HLT-1	OEM	V2403E4TDOC	HT23RTJ	-	-	1H2796997	T4	DOC	4.2.11
18185	V2403-CR-TIE4B-HLT-2	OEM	V2403E4TDOC	HA26RTJ	-	-	1H2806997	T4	DOC	4.2.11
18189	D1803-CR-E4B-AMN-1	OEM	D1803E4	ARX-2	-	Europe	1H5566995	T4	DPF	4.2.11
18191	V2403-CR-E4B-BMG-3	OEM	V2403E4T	BW124	-	-	1H5166995	T4	DPF	4.2.13
18192	D1803-CR-E4B-SSMR-3	OEM	D1803E4	V602C	-	-	1H5576995	T4	DPF	4.2.11
18193	D1803-CR-TE4B-RRSH-1	OEM	D1803E4T	SW504	-	-	1H4656995	T4	DPF	4.2.11
18195	D1803-CR-E4B-SBFU-1	OEM	D1803E4	SQ1237DK	-	-	1H5396995	T4	DPF	4.2.11
18198	D1803-CR-TE4B-SSMR-4	OEM	D1803E4T	SSA-V1002C	-	-	1H4666995	T4	DPF	4.2.16
18200	V2403-CR-TIE4B-AHFT1	OEM	V2403E4TDOC	CPCD30	-	-	1H2936997	T4	DOC	4.2.14
18201	V2403-CR-E4B-FLR-1	OEM	V2403E4T	58 Series Almond Sweeper	-	-	1H5236997	T4	DPF	4.2.14
18202	D1803-CR-TE4B-AMN-1	OEM	D1803E4T	ARX-4	-	Europe	1H4676995	T4	DPF	4.2.14
18204	V2403-CR-TE4B-HDM-1	OEM	V2403E4T	HMK62SS	-	-	1H3296997	T4	DPF	4.2.14
18205	D1803-CR-E4B-HVMT-1	OEM	D1803E4	HTP122	-	-	1H5176997	T4	DPF	4.2.15
18206	V2403-CR-TE4B-CRIH-1	OEM	V2403E4T	IC38	-	-	1H5546997	T4	DPF	4.2.15
18207	V2403-CR-TE4B-BRO-1	OEM	V2403E4T	GS3500	-	-	1H5726997	T4	DPF	4.2.18
18212	V2403-CR-E4B-CRCH-1	OEM	V2403E4T	RG30C-5	-	Japan	1H5816997	T4	DPF	4.3.3
18213	V2403-CR-TIE4B-AHFT2	OEM	V2403E4TDOC	CPCD35	-	-	1H5826997	T4	DOC	4.3.3
18214	V2403-CR-TIE4B-CRM-1	OEM	V2403E4TDOC	RT-5500	-	-	1H5766997	T4	DOC	4.3.3
18215	D1803-CR-TIE4B-GNI-1	OEM	D1803E4TDOC	TF-60	-	-	1H5806997	T4	DOC	4.3.3
18217	V2403-CR-TIE4B-BCP-1	OEM	V2403E4TDOC	BC3-6560	-	North America	1H5776997	T4	DOC	4.3.3
18219	D1803-CR-TE4B-KSR-1	OEM	D1803E4T	M5x	-	Europe	1H5916997	T4	DPF	4.3.3
18230	D1803-CR-TIE4BG-AIE1	OEM	D1803E4	AIE-D1803T.DOC-CGEN	-	-	1H5996997	T4	DOC	4.3.5
18236	D1803-CR-TIE4B-ASV-2	OEM	D1803E4TDOC	RT-40	-	North America	1H586997	T4	DOC	4.3.6
18238	V2403-CR-TE4B-SSSU-2	OEM	V2403E4T	Speed sprayer	-	-	1H4336995	T4	DPF	4.3.7
18239	D1803-CR-TIE4B-MEC-1	OEM	D1803E4TDOC	60J	-	-	1H6696997	T4	DOC	4.3.9
18240	D1803-CR-E4B-SBFU-2	OEM	D1803E4	SO1231DK	-	-	1H7036997	T4	DPF	4.3.10

18241	V2403-CR-E4B-SBFU-2	OEM	V2403E4	SQ1243DK	-	-	1H7026997	T4	DPF	4.3.10
18242	V2403-CR-E4B-LMKY-2	OEM	V2403E4	ULM270	-	-	1H6626997	T4	DPF	4.3.10
18244	V2403-CR-TIE4B-BGHE1	OEM	V2403E4TDOC	SDG40	-	-	1H7566997	T4	DOC	4.3.11
18246	D1803-CR-TIE4B-ACP-2	OEM	D1803E4TDOC	XAS 188	-	-	1H9326997	T4	DOC	4.3.12
18247	V2403-CR-TIE4B-AIE1	OEM	V2403E4TDOC	AIE-V2403T.DOC-CGEN	-	-	1H6136997	T4	DOC	4.3.12
18249	D1803-CR-TIE4B-ACP-3	OEM	D1803E4TDOC	XAS185	-	-	1H9326997	T4	DOC	19.12.16
18250	V2403-CR-TE4B-TLKW-1	OEM	V2403E4T	CL35	-	-	1H0106998	T4	DPF	20.3.20
18251	D1803-CR-TIE4B-TPMK1	OEM	D1803E4TDOC	MCP20	-	-	1H8696995	T4	DOC	20.8.6
18252	D1803-CR-TE4B-RSS-1	OEM	D1803E4T	RT508	-	-	1H0756998	T4	DPF	20.8.6
18253	V2403-CR-E4B-DYP-1	OEM	V2403E4	CC1300	-	-	1H0796998	T4	DPF	20.8.6
18254	V2403-CR-TIE4B-AHN-1	OEM	V2403E4TDOC	TIE4B-AHN-1	-	-	1H8766995	T4	DOC	20.8.6
18255	V2403-CR-E4B-CRCH-2	OEM	V2403E4	BY510	-	-	1H0996998	T4	DPF	20.9.14
18256	D1803-CR-TIE4B-PWL1	OEM	D1803E4TDOC	A25K	-	-	1H1026998	T4	DOC	20.9.14
18257	V2403-CR-TIE4B-PWL1	OEM	V2403E4TDOC	A38K	-	-	1H1036998	T4	DOC	20.9.14
18261	D1803-CR-TIE4B-MET-1	OEM	D1803E4TDOC	CR-TIE4B-MET-1	-	-	1H2216998	T4	DOC	21.4.1
18262	D1803-CR-TIE4B-KEA-3	OEM	D1803E4TDOC	CR-TIE4B-KEA-3	-	-	1H2916998	T4	DOC	21.4.1
18263	D1803-CR-TE4B-WCOS-1	OEM	D1803E4T	CR-TE4B-WCOS-1	-	-	1H9786998	T4	DPF	21.12.02
18269	V2403-CR-TE4B-EP-1	OEM	V2403E4TDOC	CR-TE4B-EP-1	-	-	1H2936898	T4	DOC	22.07.01
18270	V2403-CR-TIE4B-EP-2	OEM	V2403E4TDOC	CR-TIE4B-EP-2	-	-	1H2946898	T4	DOC	22.07.01
18274	V2403-CR-TE4B-SSMR-1	OEM	V2403E4T	CR-TE4B-SSMR-1	-	-	1H4346995	T4	DPF	22.10.01
18275	V2403-CR-TE4B-KEA-2	OEM	V2403E4TDOC	CR-TE4B-KEA-2	-	-	1H4616898	T4	DOC	22.11.01
18276	V2403-CR-TIE4B-KEA2	OEM	V2403E4T	CR-TIE4B-KEA2	-	-	1H4626898	T4	DPF	22.11.01
18278	V2403-CR-E4B-LSKY-1	OEM	V2403E4	CR-E4B-LSKY-1	-	-	1H4836898	T4	DPF	22.12.01
18279	V2403-CR-TE4B-LCN-1	OEM	V2403	CR-TE4B-LCN-1	-	-	1H4956898	T4	DOC	23.04.01
18280	V2403-CR-TE5B-SWD-3	OEM	V2403E5T	CR-TE5B-SWD-3	-	-	1H5606898	T5	DPF	23.10.01
18510	V2403-CR-TE5B-KRC-1	OEM	V2403E5T	TE5B-KRC-1	-	-	1H4306997	T5	DPF	4.3.3
18511	V2403-CR-E5B-BMG-1	OEM	V2403E5	E5B-BMG-1	-	-	1H5006997	T5	DPF	4.3.3
18512	V2403-CR-E5B-BMG-2	OEM	V2403E5	E5B-BMG-2	-	-	1H5016997	T5	DPF	4.3.3
18513	V2403-CR-E5B-HAM-1	OEM	V2403E5	E5B-HAM-1	-	-	1H4756997	T5	DPF	4.3.3
18514	D1803-CR-TE5B-AMN-1	OEM	D1803E5T	TE5B-AMN-1	-	-	1H4136997	T5	DPF	4.3.3
18515	D1803-CR-TE5B-DYP-1	OEM	D1803E5T	TE5B-DYP-1	-	-	1H4206997	T5	DPF	4.3.3
18516	D1803-CR-E5B-BMG-1	OEM	D1803E5	E5B-BMG-1	-	-	1H4856997	T5	DPF	4.3.3
18517	D1803-CR-E5B-AMN-1	OEM	D1803E5	E5B-AMN-1	-	-	1H4866997	T5	DPF	4.3.3
18518	V2403-CR-E5B-XCM-1	OEM	V2403E5	XE55U	-	-	1H5056997	T5	DPF	4.3.3
18519	V2403-CR-E5B-KSR-1	OEM	V2403E5	E5B-KSR-1	-	-	1H4956997	T5	DPF	4.3.3
18520	V2403-CR-E5B-KSR-2	OEM	V2403E5	E5B-KSR-2	-	-	1H4966997	T5	DPF	4.3.3
18521	D1803-CR-E5B-HMKY-1	OEM	D1803E5	E5B-HMKY-1	-	-	1H4816997	T5	DPF	4.3.3
18522	V2403-CR-E5B-LMKY-1	OEM	V2403E5	E5B-LMKY-1	-	-	1H4986997	T5	DPF	4.3.3
18523	V2403-CR-TE5B-RMKY-1	OEM	V2403E5T	TE5B-RMKY-1	-	-	1H4356997	T5	DPF	4.3.3
18527	V2403-CR-TE5B-PMS-1	OEM	V2403E5T	TE5B-PMS-1	-	-	1H4286997	T5	DPF	4.3.3
18528	D1803-CR-TE5B-TNT-1	OEM	D1803E5T	M30	North America	-	1H4146997	T5	DPF	4.3.4
18530	V2403-CR-TE5B-ACP-1	OEM	V2403E5T	XATS138	-	-	1H6016997	T5	DPF	4.3.4
18531	D1803-CR-TE5B-EU-XP8	OEM	D1803E5T	TE5B-EU-XP8	-	-	1H4226997	T5	DPF	4.3.4
18532	D1803-CR-E5B-EU-X8	OEM	D1803E5	E5B-EU-X8	-	-	1H4836997	T5	DPF	4.3.4
18533	V2403-CR-E5B-CRCH-1	OEM	V2403E5	E5B-CRCH-1	-	-	1H4776997	T5	DPF	4.3.4
18534	D1803-CR-TE5B-SMR-1	OEM	D1803E5T	S-15R	-	-	1H4216997	T5	DPF	4.3.4
18535	D1803-CR-E5B-SMR-1	OEM	D1803E5	S-10A	-	-	1H4826997	T5	DPF	4.3.4
18536	V2403-CR-TE5B-TXN-1	OEM	V2403E5T	AR730	-	-	1H6116997	T5	DPF	20.9.14
18538	V2403-CR-E5B-TXN-1	OEM	V2403E5	AR530,LF530/730	-	-	1H4786997	T5	DPF	20.9.14
18539	D1803-CR-E5B-HAM-1	OEM	D1803E5	H251	-	-	1H4876997	T5	DPF	4.3.5
18541	V2403-CR-TE5B-RNS-1	OEM	V2403E5T	MP653	-	-	1H6066997	T5	DPF	20.9.14
18542	V2403-CR-TE5B-EU-XP8	OEM	V2403E5T	TE5B-EU-XP8	-	-	1H6166997	T5	DPF	4.3.5
18543	V2403-CR-TE5B-TNT-1	OEM	V2403E5T	800	-	-	1H4366997	T5	DPF	4.3.5
18544	V2403-CR-TE5B-SHF-1	OEM	V2403E5T	4670series	-	-	1H6506997	T5	DPF	4.3.5
18546	V2403-CR-TE5B-BRO-1	OEM	V2403E5T	G3500	-	-	1H6156997	T5	DPF	4.3.5
18547	V2403-CR-TE5B-EU-X8	OEM	V2403E5T	TE5B-EU-X8	-	-	1H6166997	T5	DPF	4.3.6
18548	V2403-CR-E5B-EU-X8	OEM	V2403E5	E5B-EU-X8	-	-	1H6616997	T5	DPF	4.3.6
18549	V2403-CR-E5B-AUS-1	OEM	V2403E5	C251H	-	-	1H6596997	T5	DPF	4.3.6
18550	D1803-CR-E5B-DYP-1	OEM	D1803E5	CC1100/CC1200	-	-	1H6146997	T5	DPF	4.3.7
18551	V2403-CR-E5B-EU-XP8	OEM	V2403E5	E5B-EU-XP8	-	-	1H6616997	T5	DPF	4.3.9
18553	V2403-CR-E5B-SHF-1	OEM	V2403E5	4670series(E5B)	-	-	1H6806997	T5	DPF	4.3.10
18554	D1803-CR-E5B-TXN-1	OEM	D1803E5	LF550/570	-	-	1H6836997	T5	DPF	20.9.14
18555	D1803-CR-TE5B-BRO-1	OEM	D1803E5T	G2700	-	-	1H7676997	T5	DPF	4.3.11
18556	D1803-CR-TE5B-BRO-2	OEM	D1803E5T	G15048	-	-	1H7686997	T5	DPF	4.3.11
18557	D1803-CR-TE5B-MLC-1	OEM	D1803E5T	TA3	-	-	1H7596997	T5	DPF	4.3.11
18558	D1803-CR-TE5B-AUS-1	OEM	D1803E5T	D350AHG	-	-	1H7646997	T5	DPF	4.3.11
18559	V2403-CR-E5B-BHKW-1	OEM	V2403E5	40V5/50V5/60V5	-	-	1H5036997	T5	DPF	4.3.11
18560	V2403-CR-TE5B-HLT-2	OEM	V2403E5T	Delta Prometheus	-	-	1H9316997	T5	DPF	4.3.12
18561	V2403-CR-E5B-TXN-2	OEM	V2403E5	LF530/570	-	-	1H7556997	T5	DPF	19.10.17
18562	V2403-CR-TE5B-SWD-1	OEM	V2403E5T	SWL2830	-	-	1H6026997	T5	DPF	19.11.15
18566	D1803-CR-TE5B-SHF-1	OEM	D1803E5T	3650	-	-	1H0036998	T5	DPF	19.12.16
18567	D1803-CR-E5B-XCM-1	OEM	D1803E5	XMR275S	-	-	1H4886997	T5	DPF	19.12.16
18568	V2403-CR-E5B-ZDL-1	OEM	V2403E5	JCPT1823RT	-	-	1H1306997	T5	DPF	19.12.16
18569	V2403-CR-TE5B-GEO-1	OEM	V2403E5T	7822DT/6622CPT	-	-	1H0006998	T5	DPF	19.12.16
18570	D1803-CR-TE5B-RNS-1	OEM	D1803E5T	MTP Premium	-	-	1H0136998	T5	DPF	20.1.20
18571	V2403-CR-E5B-XCM-2	OEM	V2403E5	XMR403	-	-	1H0176998	T5	DPF	20.1.20
18573	V2403-CR-TE5B-TFT-1	OEM	V2403E5T	9L PLUS FD20-36	-	-	1H0126998	T5	DPF	20.3.20
18574	D1803-CR-E5B-SHF-1	OEM	D1803E5	3650(E5B)	-	-	1H0116998	T5	DPF	20.1.20
18575	D1803-CR-E5B-RNS-1	OEM	D1803E5	HR300	-	-	1H0086998	T5	DPF	20.1.20
18576	D1803-CR-TE5B-KEA-1/2	OEM	D1803E5T	TE5B-KEA-1/2	-	-	1H0076998	T5	DPF	20.1.20
18578	V2403-CR-TE5B-HLT-1	OEM	V2403E5T	HT23RTJ	-	-	1H0066998	T5	DPF	20.1.20
18580	D1803-CR-TE5B-DCI-1	OEM	D1803E5T	Micro Apollo	-	-	1H0046998	T5	DPF	20.1.20
18588	V2403-CR-E5B-AHFT-1	OEM	V2403E5	E5B-AHFT-1	-	-	1H0266998	T5	DPF	20.8.6
18589	V2403-CR-E5B-AHFT-3	OEM	V2403E5	E5B-AHFT-3	-	-	1H0276998	T5	DPF	20.8.6
18590	V2403-CR-E5B-HNW-1	OEM	V2403E5	KC300	-	-	1H0246998	T5	DPF	20.8.6
18593	V2403-CR-TE5B-KSR-1	OEM	V2403E5T	M65	-	-	1H0226998	T5	DPF	20.8.6
18594	V2403-CR-TE5B-COM-1	OEM	V2403E5T	CB4	-	-	1H0766998	T5	DPF	20.8.6
18595	D1803-CR-E5B-RNS-2	OEM	D1803E5	MTP Standard	-	-	1H0776998	T5	DPF	20.8.6
18596	V2403-CR-TE5B-AHFT-1	OEM	V2403E5T	CPCC35-KU20H	-	-	1H0806998	T5	DPF	20.8.6
18597	V2403-CR-TE5B-AHFT-2	OEM	V2403E5T	CPCC35-KU19G2	-	-	1H0816998	T5	DPF	20.8.6
18598	V2403-CR-E5B-DYP-1	OEM	V2403E5	CC1300	-	-	1H0786998	T5	DPF	20.8.6
18603	V2403-CR-TE5B-HDM-1	OEM	V2403E5T	TE5B-HDM-1	-	-	1H4326997	T5	DPF	21.5.1
18604	D1803-CR-TE5B-GNI-1	OEM	D1803E5T	TE5B-GNI-1	-	-	1H0846998	T5	DPF	20.8.6
18605	V2403-CR-TE5B-SHF-2	OEM	V2403E5T	TE5B-SHF-2	-	-	1H0836998	T5	DPF	20.8.6
18606	V2403-CR-E5B-JSQ-1	OEM	V2403E5	E5B-JSQ-1	-	-	1H0866998	T5	DPF	20.8.6
18607	D1803-CR-E5B-MLNK-1	OEM	D1803E5	E5B-MLNK-1	-	-	1H0856998	T5	DPF	20.8.6
18609	D1803-CR-E5B-JSQ-1	OEM	D1803E5	SO830	-	-	1H0986998	T5	DPF	20.8.6
18610	V2403-CR-E5B-AHFT-5	OEM	V2403E5	H3	-	-	1H0966998	T5	DPF	20.8.6

18611	V2403-CR-TE5B-SWD-2	OEM	V2403E5T	SWSL2023RT	-	-	1H1016998	T5	DPF	20.9.14
18612	D1803-CR-TE5B-MLC-2	OEM	D1803E5T	3MDX	-	-	1H1006998	T5	DPF	20.9.14
18613	V2403-CR-TE5B-SMP-1	OEM	V2403E5T	50ZT	-	-	1H0956998	T5	DPF	20.9.14
18614	D1803-CR-TE5B-SMP-1	OEM	D1803E5T	36ZT/40ZT	-	-	1H0946998	T5	DPF	20.9.14
18615	D1803-CR-E5B-SBFU-1	OEM	D1803E5	E5B-SBFU-1	-	-	1H1956998	T5	DPF	21.1.25
18616	V2403-CR-E5B-ZML-2	OEM	V2403E5	E5B-ZML-2	-	-	1H1996998	T5	DPF	21.1.25
18617	V2403-CR-TE5B-AHFT-3	OEM	V2403E5T	TE5B-AHFT-3	-	-	1H2006998	T5	DPF	21.1.25
18618	D1803-CR-TIE5B-SHF-1	OEM	D1803E5T	TIE5B-SHF-1	-	-	1H4616997	T5	DPF	21.1.25
18619	D1803-CR-TE5B-DIB-1	OEM	D1803E5T	JMB-M-500	-	-	1H1686998	T5	DPF	21.1.25
18620	V2403-CR-TE5B-ZML-1	OEM	V2403	CR-TE5B-ZML-1	-	-	1H2186998	T5	DPF	21.3.1
18621	D1803-CR-TE5B-VNI-2	OEM	D1803	CR-TE5B-VNI-2	-	-	1H2196998	T5	DPF	21.3.1
18624	D1803-CR-TE5B-HLT-1	OEM	D1803	CR-TE5B-HLT-1	-	-	1H2236998	T5	DPF	21.5.1
18625	D1803-CR-TE5B-AWC-1	OEM	D1803	CR-TE5B-AWC-1	-	-	1H2946998	T5	DPF	21.5.1
18626	V2403-CR-E5B-ZML-1	OEM	V2403	CR-E5B-ZML-1	-	-	1H2956998	T5	DPF	21.5.1
18628	V2403-CR-E5B-LGL-1	OEM	V2403E5	CR-E5B-LGL-1	-	-	1H3706998	T5	DPF	21.06.01
18629	V2403-CR-E5B-LGL-2	OEM	V2403E5	CR-E5B-LGL-2	-	-	1H3716998	T5	DPF	21.06.01
18630	D1803-CR-TE5B-VNI-1	OEM	D1803E5T	CR-TE5B-VNI-1	-	-	1H3736998	T5	DPF	21.06.01
18631	V2403-CR-E5B-ZML-3	OEM	V2403E5	CR-E5B-ZML-3	-	-	1H5786998	T5	DPF	21.06.01
18632	V2403-CR-E5B-LGL-3	OEM	V2403E5	CR-E5B-LGL-3	-	-	1H5796998	T5	DPF	21.06.01
18634	V2403-CR-E5B-XCM-3	OEM	V2403E5	CR-E5B-XCM-3	-	-	1H6706998	T5	DPF	21.08.01
18635	V2403-CR-E5B-CNFK-1	OEM	V2403E5	CR-E5B-CNFK-1	-	-	1H6766998	T5	DPF	21.08.01
18636	V2403-CR-E5B-GFR-1	OEM	V2403E5	CR-E5B-GFR-1	-	-	1H6836998	T5	DPF	21.09.01
18637	D1803-CR-TE5B-HLT-2	OEM	D1803E5T	CR-TE5B-HLT-2	-	-	1H6886998	T5	DPF	21.09.01
18638	V2403-CR-TE5B-AMN-1	OEM	V2403E5T	CR-TE5B-AMN-1	-	-	1H6896998	T5	DPF	21.09.01
18639	V2403-CR-E5B-XCM-5	OEM	V2403E5	XGA18E	-	-	1H7536998	T5	DPF	21.12.01
18646	V2403-CR-TE5B-UNF-1	OEM	V2403E5T	FD35T/NJV1	-	-	1H9776998	T5	DPF	22.01.01
18649	V2403-CR-E5B-XCM-4	OEM	V2403E5	CR-E5B-XCM-4	-	-	1H0006898	T5	DPF	22.07.01
18650	D1803-CR-E5B-RRBM-1	OEM	D1803E5	CR-E5B-RRBM-1	-	-	1H2296898	T5	DPF	22.07.01
18651	V2403-CR-TE5B-XHF-1	OEM	V2403E5T	CR-TE5B-XHF-1	-	-	1H2316898	T5	DPF	22.07.01
18652	V2403-CR-TE5B-CRKW-1	OEM	V2403E5T	CR-TE5B-CRKW-1	-	-	1H2876898	T5	DPF	22.07.01
18653	V2403-CR-TE5B-TFT-2	OEM	V2403E5T	CR-TE5B-TFT-2	-	-	1H2976898	T5	DPF	22.08.01
18654	V2403-CR-E5B-AFHN-1	OEM	V2403E5	CR-E5B-AFHN-1	-	-	1H3646898	T5	DPF	22.09.01
18655	D1803-CR-TE5B-SNY-1	OEM	D1803E5T	CR-TE5B-SNY-1	-	-	1H4596898	T5	DPF	22.10.01
18656	V2403-CR-TE5B-SKL-1	OEM	V2403E5T	CR-TE5B-SKL-1	-	-	1H3636898	T5	DPF	22.12.01
18657	V2403-CR-TE5B-LGF-1	OEM	V2403E5T	CR-TE5B-LGF-1	-	-	1H4826898	T5	DPF	22.12.01
18658	V2403-CR-TE5B-ZML-2	OEM	V2403E5T	CR-TE5B-ZML-2	-	-	1H4856898	T5	DPF	23.01.01
18659	V2403-CR-E5B-JSQ-2	OEM	V2403E5	CR-E5B-JSQ-2	-	-	1H4906898	T5	DPF	23.01.01
18660	V2403-CR-E5B-CRKW-6	OEM	V2403E5	CR-E5B-CRKW-6	-	-	1H4886898	T5	DPF	23.02.01
18661	V2403-CR-TE5B-EPS-1	OEM	V2403E5T	CR-TE5B-EPS-1	-	-	1H4966898	T5	DPF	23.04.01
18666	V2403-CR-E5B-HZM-1	OEM	V2403E5	CR-E5B-HZM-1	-	-	1H5406898	T5	DPF	23.07.01
18671	V2403-CR-TE5B-TFT-3	OEM	V2403E5T	CR-TE5B-TFT-3	-	-	1H8556998	T5	DPF	24.01.01
18672	V2403-CR-TE5B-AHFT-4	OEM	V2403E5T	CR-TE5B-AHFT-4	-	-	1H5616898	T5	DPF	24.01.01
18900	V2403-CR-TE5BG2-SAE2	OEM	V2403E5TBG	TE5BG2-SAE2	-	-	1H6716997	T5	DPF	20.8.6
18901	V2403-CR-TE5BG2-ACP1	OEM	V2403E5TBG	QAS30	-	-	1H1066998	T5	DPF	20.10.30

★ addition  
★ addition

#### D902 series

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
18801	D902-K-E4B-KGS-1	OEM	D902	K-E4B-KGS-1	-	-	1H7706998	T4	NONE	23.03.01
18804	D902-K-E4B-CBH-1	OEM	D902	K-E4B-CBH-1	-	-	1H7906998	T4	NONE	23.03.01
18805	V2403-CR-E5B-XCM-6	OEM	V2403E5	CR-E5B-XCM-6	-	-	1H5066997	T5	DPF	23.06.01
18806	D1803-CR-TE5B-XCM-1	OEM	D1803E5T	CR-TE5B-XCM-1	-	-	1H5256898	T5	DPF	23.06.01

#### V1505 series(T4)

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
19004	V1505-T-E4B-VMR-1	OEM	V1505	T-E4B-VMR-1	North America	-	1H5716995	T4	DPF05	3.3.2
19006	V1505-T-E4B-DWC-1	OEM	V1505	T-E4B-DWC-1	-	-	1H5726995	T4	DPF05	3.3.5
19014	V1505-T-E4B-LMKY-1	OEM	V1505	LM551	-	-	1H5736995	T4	DPF05	4.2.18

#### Update history

Ver	Contents
24.01.01	• Addition of the model to support.
23.11.02	• Fixed wrong menu for one BG type model.
23.11.01	• Addition of the model to support. • Following steps have been taken to fix bug. Following data monitor items have been removed for some models, EGR Differential Pressure EGR Differential Pressure Output Voltage And the following data monitor items have been added. Intake Air Temperature built-in MAF Intake Air Temperature built-in MAF Output Voltage
23.10.02	• Addition of the model to support.
23.10.01	• Addition of the model to support.
23.08.01	• Addition of the model to support.
23.07.01	• Addition of the model to support.
23.06.01	• Addition of the model to support.
23.05.01	• Addition of the model to support.
23.04.01	• Addition of the model to support.
23.03.02	• Fixed an issue where diagnosis could not be started in O3 series.
23.03.01	• Addition of the model to support. • The D902 series only supports Japanese and English in this version.
23.02.01	• Addition of the model to support.