

Release Notes

Filename:

Diagmaster_DataBase_23.10.01.00_for_Nonself.exe

Improvements/Enhancements of this version:

- Addition of the model to support.

Supported Engines

V38, V1505CRS and 07 series

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
6047	V3800DICR-TI-E3B-YB1	OEM	V3800	DGM600MK-P	Japan	-	1H0406995	T3	NONE	4.3.0
6048	V3800DICR-TI-E3B-YB2	OEM	V3800	DGM600	Japan	-	1H2486995	T3	NONE	4.3.0
6054	V3800DICR-TE3B-CRMO1	OEM	V3800	CRMO1	Japan	-	1H0316995	T3	NONE	4.3.0
6055	V3800DICR-TIE3B-HN1	OEM	V3800	HN1	Japan	-	1H6806995	T3	NONE	4.3.0
6056	V3800DICR-TI-E3B-DE1	OEM	V3800	DE1	Japan	-	1H6856995	T3	NONE	4.3.0
6057	V3800DICR-TI-E3B-DE2/DE3	OEM	V3800	DE2	Japan	-	1H8036995	T3	NONE	4.3.0
6058	V3800DICR-TI-E3B-NS1	OEM	V3800	NES60TKL	-	-	1H8306995	T3	NONE	4.1.2
6107	V3800-CR-TE4CB-VMR-1/1R	OEM	V3800	D20x22	-	-	1H1816995	T4	DPF	3.3.1
6109	V3800-CR-TE4B-BMG-1	OEM	V3800	TE4B-BMG-1	-	-	1H1646995	T4	DPF	4.3.0
6110	V3800-CR-TE4B-DCI-1	OEM	V3800	TE4B-DCI-1	-	-	1H1636995	T4	DPF	4.3.0
6112	V3800-CR-TE4B-EPS-1	OEM	V3800	TE4B-EPS-1	-	-	1H1656995	T4	DPF	4.3.0
6113	V3800-CR-TE4B-MRO-1	OEM	V3800	TE4B-MRO-1	-	-	1H1666995	T4	DPF	4.3.0
6114	V3800-CR-TE4B-MRO-2	OEM	V3800	TE4B-MRO-2	-	-	1H1676995	T4	DPF	4.3.0
6127	V3800-CR-TIE4B-BGHE1	OEM	V3800	TIE4B-BGHE1	-	-	1H7266995	T4	DPF	4.3.0
6129	V3800-CR-TIE4B-DCI-1	OEM	V3800	TIE4B-DCI-1	-	-	1H1106995	T4	DPF	4.3.0
6130	V3800-CR-TIE4B-BMG-1	OEM	V3800	TIE4B-BMG-1	-	-	1H1116995	T4	DPF	4.3.0
6131	V3800-CR-TE4B-EPS-2	OEM	V3800	TE4B-EPS-2	-	-	1H1686995	T4	DPF	4.3.0
6132	V3800-CR-TE4B-AFHN1/2	OEM	V3800	TE4B-AFHN1/2	-	-	1H7016995	T4	DPF	4.3.0
6137	V3800-CR-TE4B-RRSH1	OEM	V3800	TE4B-RRSH1	-	-	1H1846995	T4	DPF	4.3.0
6138	V3800-CR-TIE4B-RRSH1	OEM	V3800	TIE4B-RRSH1	-	-	1H1236995	T4	DPF	4.3.0
6144	V3800-CR-TIE4B-AUS-1	OEM	V3800	TIE4B-AUS-1	-	-	1H1136995	T4	DPF	4.3.0
6149	V3800-CR-TIE4CB-KSR1	OEM	V3800	N115	Europe	-	1H1126995	T4	DPF	4.3.0
6150	V3800-CR-TE4B-DCI-2	OEM	V3800	TE4B-DCI-2	-	-	1H1696995	T4	DPF	4.3.0
6151	V3800-CR-TIE4B-DCI-2	OEM	V3800	TIE4B-DCI-2	-	-	1H1146995	T4	DPF	4.3.0
6153	V3800-CR-TE4B-MAT-1	OEM	V3800	TE4B-MAT-1	-	-	1H7026995	T4	DPF	4.3.0
6155	V3800-CR-TE4B-CRMO1	OEM	V3800	MST-700VDL	Japan	-	1H1866995	T4	DPF	4.1.2
6158	V3800-CR-TE4B-RRSH2	OEM	V3800	MW703	-	-	1H1886995	T4	DPF	4.1.5
6159	V3800-CR-TE4B-HOF-1	OEM	V3800	H33-4	-	-	1H0576997	T4	DPF	4.1.5
6161	V3800-CR-TE4B-EPS-3	OEM	V3800	TE4B-EPS-3	-	-	1H7036995	T4	DPF	4.1.5
6162	V3800-CR-TE4B-ANT-S1	OEM	V3800	TE4B-ANT-S1	-	-	1H0656997	T4	DPF	4.1.5
6165	V3800-CR-TE4B-BCS-S1	OEM	V3800	TE4B-BCS-S1	-	-	1H0826997	T4	DPF	4.2.0
6166	V3800-CR-TIE4B-ITC-1/2/3	OEM	V3800	TIE4B-ITC-1	Italy	-	1H1156995	T4	DPF	4.2.0
6171	V3800-CR-TE4B-ANT-1	OEM	V3800	TGF 10900	-	-	1H0986997	T4	DPF	4.2.2
6172	V3800-CR-TE4B-BCS-1	OEM	V3800	Volcan V950AR	-	-	1H0996997	T4	DPF	4.2.2
6173	V3800-CR-TE4B-SSMR1	OEM	V3800	BSA3000	-	-	1H0036997	T4	DPF	4.2.2
6175	V3800-CR-TIE4B-CRIF1	OEM	V3800	U-4D	-	-	1H1246995	T4	DPF	4.2.3
6180	V3800-CR-TE4B-RRSH3	OEM	V3800	TZ704	-	-	1H7046995	T4	DPF	4.2.7
6181	V3800-CR-TE4B-BHIF1	OEM	V3800	CT-500	Japan	-	1H1896995	T4	DPF	4.2.8
6182	V3800-CR-TE4B-ANT-2	OEM	V3800	TGF9000	-	-	1H2216995	T4	DPF	4.2.9
6187	V3800-CR-TE4B-ANT-3	OEM	V3800	TGF7900	-	-	1H2386997	T4	DPF	4.2.10
6188	V3800-CR-TE4B-AFHN3	OEM	V3800	F45C5	Japan	-	1H7056995	T4	DPF	4.2.16
6189	V3800-CR-TE4B-HMCH1	OEM	V3800	CG750	-	-	1H7066995	T4	DPF	4.2.17
6215	V3800-CR-TE4B-CSPB-1	OEM	V3800	CR-TE4B-CSPB-1	-	-	1H6136998	T4	DPF	22.11.01
6217	V3800-CR-TIE4B-ZML-1	OEM	V3800	CR-TIE4B-ZML-1	-	-	1H5936998	T4	DPF	23.03.01
6220	V3800-CR-TE4B-SWD2-1	OEM	V3800	CR-TE4B-SWD2-1	-	-	1H6566998	T4	DPF	23.07.01
6222	V3800-CR-TIE4B-HE2-1	OEM	V3800	CR-TIE4B-HE2-1	-	-	1H5836998	T4	DPF	23.10.01
6401	V3800DICR-TIE3B-ACC1	OEM	V3800	TIE3B-ACC1	-	-	1H6856995	T3	NONE	4.2.2
6402	V3800DICR-TI-E3B-DE4	OEM	V3800	DIS-80VPB	-	-	1H1816997	T3	NONE	4.2.4
6414	V3800DICR-TI-E3B-DE5	OEM	V3800	DCA-60LSKE-D2	-	-	1H6496997	T3	NONE	4.3.10
6503	V3800DICR-TIE3B-HE1	OEM	V3800	PDS400	-	-	1H0896997	T3(E4)	NONE	4.2.1
6505	V3800-CR-TE3B-MAT-1	OEM	V3800	Azura MC 210	-	-	1H0636997	T3(E4)	NONE	4.2.3
6512	V3800DICR-TIE3B-HE-2	OEM	V3800	TIE3B-HE-2	-	-	1H1746998	T3	NONE	21.1.25
6513	V3800DICR-TIE3B-SH1	OEM	V3800	V3800DICR-TIE3B-SH1	-	-	1H8806998	T3(E4)	NONE	21.12.02
6704	V1505-CR-TE5-ACP-1	OEM	V1505CRS	XAS88	-	-	1H6196997	T5	DPF	19.12.16
6705	V1505-CR-TE5B-RNS-1	OEM	V1505CRS	Fairway305/405	-	-	1H6216997	T5	DPF	20.8.6
6706	V1505-CR-TE5B-EU-Z1	OEM	V1505CRS	TE5B-EU-Z1	-	-	1H6206997	T5	DPF	20.8.6
6707	V1505-CR-TE5B-LMKY-1	OEM	V1505CRS	LM551B	-	-	1H6226997	T5	DPF	20.8.6
6708	V1505-CR-TE5B-RIO-1	OEM	V1505	Sweepers City Jet	-	-	1H6236997	T5	DPF	20.11.30
6709	V1505-CR-TE5B-SEE-1	OEM	V1505	Wood Chipper	-	-	1H6246997	T5	DPF	20.11.30
6712	V1505-CR-TE5B-PES-1	OEM	V1505CRS	TE5B-PES-1	-	-	1H6256997	T5	DPF	21.1.25
6713	V1505-CR-TE5B-COM-1	OEM	V1505	CR-TE5B-COM-1	-	-	1H1276998	T5	DPF	21.2.1
6714	V1505-CR-TE5B-MAC-1	OEM	V1505	TE5B-MAC-1	-	-	1H6266997	T5	DPF	21.2.1
6716	V1505-CR-TE5B-CMG-1	OEM	V1505CRS	CR-TE5B-CMG-1	-	-	1H1286998	T5	DPF	21.4.1
6718	V1505-CR-TE5B-SSSU-1	OEM	V1505CRS	CR-TE5B-SSSU-1	-	-	1H6386997	T5	DPF	21.09.01
6719	V1505-CR-TE5B-AVN-1	OEM	V1505CRS	CR-TE5B-AVN-1	-	-	1H1296998	T5	DPF	21.12.01
6723	V1505-CR-TE5B-KEA-1	OEM	V1505CRS	CR-TE5B-KEA-1	-	-	1H1306998	T5	DPF	22.04.01
6724	V1505-CR-TE5B-ERM-1	OEM	V1505CRS	CR-TE5B-ERM-1	-	-	1H1316998	T5	DPF	22.04.01
6725	V1505-CR-TE5B-DSV-1	OEM	V1505CRS	CR-TE5B-DSV-1	-	-	1H1326998	T5	DPF	22.05.01
6730	V1505-CR-TE5B-GEO-1	OEM	V1505CRS	CR-TE5B-GEO-1	-	-	1H0216898	T5	DPF	22.07.01
6731	V1505-CR-TE5B-SEE-2	OEM	V1505CRS	CR-TE5B-SEE-2	-	-	1H1336998	T5	DPF	22.12.01
6732	V1505-CR-TE5B-BRO-1	OEM	V1505CRS	CR-TE5B-BRO-1	-	-	1H1346998	T5	DPF	23.08.01
6733	V1505-CR-TE5B-EUZ1-2	OEM	V1505CRS	CR-TE5B-EUZ1-2	-	-	1H5426898	T5	DPF	23.08.01
7022	V3307-CR-TE4B-BMG-1	OEM	V3307	TE4B-BMG-1	-	-	1H2726995	T4	DPF	4.3.0
7023	V3307-CR-TE4B-DYP-1	OEM	V3307	TE4B-DYP-1	-	-	1H2806995	T4	DPF	4.3.0
7024	V3307-CR-T-E4B-BMG-2	OEM	V3307	TE4B-BMG-2	-	-	1H2736995	T4	DPF	4.3.0
7028	V3307-CR-TE4B-DCI-1	OEM	V3307	TE4B-DCI-1	-	-	1H2556995	T4	DPF	4.3.0
7029	V2607-CR-TE4B-AEB-1	OEM	V2607	TE4B-AEB-1	-	-	1H3026995	T4	DPF	4.3.0
7036	V3307-CR-TE4B-HAM-1	OEM	V3307	TE4B-HAM-1	-	-	1H2826995	T4	DPF	4.3.0
7037	V3307-CR-TE4B-HAM-2	OEM	V3307	TE4B-HAM-2	-	-	1H2836995	T4	DPF	4.3.0
7038	V2607-CR-TE4B-BRG-1	OEM	V2607	TE4B-BRG-1	-	-	1H3036995	T4	DPF	4.3.0
7039	V3307-CR-TE4B-AIE-1	OEM	V3307	TE4B-AIE-1	-	-	1H2746995	T4	DPF	4.3.0
7043	V3307-CR-TE4B-RRSH1/RRSH2	OEM	V3307	R2-4	-	-	1H2856995	T4	DPF	4.1.1
7044	V3307-CR-TE4B-TCKH1	OEM	V3307	MS-32	-	-	1H2566995	T4	DPF	4.1.1
7049	V2607-CR-TE4B-DMD-1	OEM	V2607	TE4B-DMD-1	-	-	1H3056995	T4	DPF	4.1.2

★ addition

18629	V2403-CR-E5B-LGL-2	OEM	V2403E5	CR-E5B-LGL-2	-	-	1H3716998	T5	DPF	21.06.01
18630	D1803-CR-TE5B-VNI-1	OEM	D1803E5T	CR-TE5B-VNI-1	-	-	1H3736998	T5	DPF	21.06.01
18631	V2403-CR-E5B-ZML-3	OEM	V2403E5	CR-E5B-ZML-3	-	-	1H5786998	T5	DPF	21.06.01
18632	V2403-CR-E5B-LGL-3	OEM	V2403E5	CR-E5B-LGL-3	-	-	1H5796998	T5	DPF	21.06.01
18634	V2403-CR-E5B-XCM-3	OEM	V2403E5	CR-E5B-XCM-3	-	-	1H6706998	T5	DPF	21.08.01
18635	V2403-CR-E5B-CNFK-1	OEM	V2403E5	CR-E5B-CNFK-1	-	-	1H6766998	T5	DPF	21.08.01
18636	V2403-CR-E5B-GFR-1	OEM	V2403E5	CR-E5B-GFR-1	-	-	1H6836998	T5	DPF	21.09.01
18637	D1803-CR-TE5B-HLT-2	OEM	D1803E5T	CR-TE5B-HLT-2	-	-	1H6886998	T5	DPF	21.09.01
18638	V2403-CR-TE5B-AMN-1	OEM	V2403E5T	CR-TE5B-AMN-1	-	-	1H6896998	T5	DPF	21.09.01
18639	V2403-CR-E5B-XCM-5	OEM	V2403E5	XGA18E	-	-	1H7536998	T5	DPF	21.12.01
18646	V2403-CR-TE5B-UNF-1	OEM	V2403E5T	FD35T/NJV1	-	-	1H9776998	T5	DPF	22.01.01
18649	V2403-CR-E5B-XCM-4	OEM	V2403E5	CR-E5B-XCM-4	-	-	1H0006898	T5	DPF	22.07.01
18650	D1803-CR-E5B-RRBM-1	OEM	D1803E5	CR-E5B-RRBM-1	-	-	1H2296898	T5	DPF	22.07.01
18651	V2403-CR-TE5B-XHF-1	OEM	V2403E5T	CR-TE5B-XHF-1	-	-	1H2316898	T5	DPF	22.07.01
18652	V2403-CR-TE5B-CRKW-1	OEM	V2403E5T	CR-TE5B-CRKW-1	-	-	1H2876898	T5	DPF	22.07.01
18653	V2403-CR-TE5B-TFT-2	OEM	V2403E5T	CR-TE5B-TFT-2	-	-	1H2976898	T5	DPF	22.08.01
18654	V2403-CR-E5B-AFHN-1	OEM	V2403E5	CR-E5B-AFHN-1	-	-	1H3646898	T5	DPF	22.09.01
18655	D1803-CR-TE5B-SNY-1	OEM	D1803E5T	CR-TE5B-SNY-1	-	-	1H4596898	T5	DPF	22.10.01
18656	V2403-CR-TE5B-SKL-1	OEM	V2403E5T	CR-TE5B-SKL-1	-	-	1H3636898	T5	DPF	22.12.01
18657	V2403-CR-TE5B-LGF-1	OEM	V2403E5T	CR-TE5B-LGF-1	-	-	1H4826898	T5	DPF	22.12.01
18658	V2403-CR-TE5B-ZML-2	OEM	V2403E5T	CR-TE5B-ZML-2	-	-	1H4856898	T5	DPF	23.01.01
18659	V2403-CR-E5B-JSQ-2	OEM	V2403E5	CR-E5B-JSQ-2	-	-	1H4906898	T5	DPF	23.01.01
18660	V2403-CR-E5B-AHFT-6	OEM	V2403E5	CR-E5B-AHFT-6	-	-	1H4886898	T5	DPF	23.02.01
18661	V2403-CR-TE5B-EPS-1	OEM	V2403E5T	CR-TE5B-EPS-1	-	-	1H4966898	T5	DPF	23.04.01
18666	V2403-CR-E5B-HZM-1	OEM	V2403E5	CR-E5B-HZM-1	-	-	1H5406898	T5	DPF	23.07.01
18900	V2403-CR-TE5BG2-SAE2	OEM	V2403E5TBG	TE5BG2-SAE2	-	-	1H6716997	T5	DPF	20.8.6
18901	V2403-CR-TE5BG2-ACP1	OEM	V2403E5TBG	QAS30	-	-	1H1066998	T5	DPF	20.10.30

D902 series

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
18801	D902-K-E4B-KGS-1	OEM	D902	K-E4B-KGS-1	-	-	1H7706998	T4	-	23.03.01
18804	D902-K-E4B-CBH-1	OEM	D902	K-E4B-CBH-1	-	-	1H7906998	T4	-	23.03.01
18805	V2403-CR-E5B-XCM-6	OEM	V2403E5	CR-E5B-XCM-6	-	-	1H5066997	T5	DPF	23.06.01
18806	D1803-CR-TE5B-XCM-1	OEM	D1803E5T	CR-TE5B-XCM-1	-	-	1H5256898	T5	DPF	23.06.01

V1505 series(T4)

#	Engine Model(Vehicle Model)	Model	Engine	Option1	Option2	Option3	Software ID	Rank	ATU	Available from
19004	V1505-T-E4B-VMR-1	OEM	V1505	T-E4B-VMR-1	North America	-	1H5716995	T4	DPF05	3.3.2
19006	V1505-T-E4B-DWC-1	OEM	V1505	T-E4B-DWC-1	-	-	1H5726995	T4	DPF05	3.3.5
19014	V1505-T-E4B-LMKY-1	OEM	V1505	LM551	-	-	1H5736995	T4	DPF05	4.2.18

Update history

Ver	Contents
23.10.01	•Addition of the model to support.
23.08.01	•Addition of the model to support.
23.07.01	•Addition of the model to support.
23.06.01	•Addition of the model to support.
23.05.01	•Addition of the model to support.
23.04.01	•Addition of the model to support.
23.03.02	•Fixed an issue where diagnosis could not be started in O3 series.
23.03.01	•Addition of the model to support. •The D902 series only supports Japanese and English in this version.
23.02.01	•Addition of the model to support.
23.01.01	•Addition of the model to support.
22.12.01	•Addition of the model to support.
22.11.01	•Addition of the model to support.