



KS 45 "BRIGGS & STRATTON"

WIRING DIAGRAM	
A	Horn push button
B	Switch
C	Filter-shaker push button
D	Negative pole
E	Electromagnetic switch
F	Negative pole
G	Battery 12V- 45A
H	Engine Briggs & S.
L	Microswitch
M	Safety switch *
N	Electric filter shaker
P	Horn
Q	Clamp
R	Diode 3A
S	Fuse 16A
T	Intermittent lamp
U	Microswitch

\* OPTIONAL