

Technical Service Bulletin

Date: January 31, 2007
To: Minuteman Dealers and Service Centers
From: The Technical Support Department
Regarding: E260 and E320 Squeegee Mechanism 260660

The Squeegee Mechanism on the E260 and E320 part number 260660 has been updated.

The entire assembly should be replaced with new style, if the old style fails in the field.

Some parts of the new style are not inter-changeable with older assemblies.

