



















CM 1650












Engine Diagnosis

	Service PC	HDS ² ET-Nr. 03503250 	Sontheim Interface Can FOX ET- Nr. 3502430 	Hako Diagnostic cable OBD 2 CAN 2 (black) Part-No. 03502750 
alternative	Service PC	HDS ² ET-Nr. 03503250 	Sontheim Interface Can USB Part-No. 03501750 	Hako Diagnostic cable OBD 2 CAN 2 (black) with the adapter Part-No. 03502750 
alternative	Service PC	HDS ² ET-Nr. 03503250 	Sontheim Interface Can USB Part-No. 03501750 	Diagnostic cable black Part-No. 03501760 

Vehicle Diagnosis

	Service PC	Hako Diagnose the latest version 	Sontheim Interface Can USB Part-No. 03501750 	Diagnostic cable red Part-No. 03501900 
alternative	Service PC	Hako Diagnose the latest version 	Sontheim Interface Can USB Part-No. 03501750 	Hako Diagnostic cable OBD 2 CAN 1 (red) with the adapter Part-No. 03502750 
alternative	Service PC	Hako Diagnose the latest version 	Sontheim Interface Can FOX Part-No. 03502430 	Hako Diagnostic cable OBD 2 CAN 1 (red) Part-No. 03502750 

Diagnosis Hydrostat

	Service PC	Bodas after 3.4 	Bodas Dongel Part-No. 0403964000 	Sontheim Interface Can USB Part-No. 03501750 	Diagnostic cable red Part-No. 03501900 
alternative	Service PC	Bodas after 3.4 	Bodas Dongel Part-No. 0403964000 	Sontheim Interface Can USB Part-No. 03501750 	Hako Diagnostic cable OBD 2 CAN 1 (red) with the adapter Part-No. 03502750 
alternative	Service PC	Bodas after 3.4 	Bodas Dongel Part-No. 0403964000 	Sontheim Interface Can FOX Part-No. 03502430 	Hako Diagnostic cable OBD 2 CAN 1 (red) Part-No. 03502750 