


## **Installation Instructions**


Wire Assy, Horn Fix Part #260685

Replacing Faulty Horn
Circuit Diode, Capacitor On
X3 Harness

Cut X3 harness wires XS34 and XS35 right behind the diode assembly. Remove and discard Diode/Capacitor portion of harness.



CUT HERE



Install female connector (supplied) to X3 harness wire labeled XS34.





Install male connector (supplied) to X3 harness wire labeled XS35.





## **Connect wires and reinstall into machine.**



